



**Technical Service
Information Bulletin**
December 16, 2004

Title:

SENSOR INSPECTION FOR AIR CONDITIONING SYSTEM

Models:

'90 – Current All Models

TSIB
AC005-04

HEATING & AIR CONDITIONING

Introduction This service bulletin contains inspection procedures to more precisely confirm proper operation of the following temperature sensors of the air conditioning system. Follow the procedures in this service bulletin when inspecting these sensors. These contents will be reflected in future repair manuals.

- Room Temperature Sensor
- Ambient Temperature Sensor
- Air Duct Sensor
- Evaporator Temperature Sensor
- Solar Sensor
- Room Humidity Sensor

Applicable Vehicles • All 1990 – Current model year **Lexus** vehicles.

**Warranty
Information**

OP CODE	DESCRIPTION	TIME	OFP	T1	T2
N/A	Not Applicable to Warranty	–	–	–	–




Lexus Supports ASE Certification

**Inspection
Procedure**
1. Inspect Room Temperature Sensor.
A. Measure the sensor resistance.

Resistance Value at 77°F (25°C)	1700 +/- 85Ω
------------------------------------	--------------


NOTE:

- Even slightly touching the sensor may change the resistance value. Be sure to hold the connector of the sensor.
- When measuring, the sensor temperature must be the same as the ambient temperature.


HINT:

As the temperature increases, the resistance decreases.

TEMPERATURE °F (°C)	SPECIFICATION kΩ
50 (10)	3.00 to 3.73
59 (15)	2.45 to 2.88
68 (20)	1.95 to 2.30
77 (25)	1.60 to 1.80
86 (30)	1.28 to 1.47
95 (35)	1.00 to 1.22
104 (40)	0.80 to 1.00
113 (45)	0.65 to 0.85
122 (50)	0.50 to 0.70
131 (55)	0.44 to 0.60
140 (60)	0.36 to 0.50



**Inspection
Procedure
(Continued)**


**2. Inspect Ambient
Temperature Sensor.**

A. Measure the sensor resistance according to the selected graph (specification).

Resistance Value at 77°F (25°C)	1700 +/- 85Ω
------------------------------------	--------------

NOTE:


- Even slightly touching the sensor may change the resistance value. Be sure to hold the connector of the sensor.
- When measuring, the sensor temperature must be the same as the ambient temperature.



HINT:

As the temperature increases, the resistance decreases.

TEMPERATURE °F (°C)	SPECIFICATION kΩ
50 (10)	3.00 to 3.73
59 (15)	2.45 to 2.88
68 (20)	1.95 to 2.30
77 (25)	1.60 to 1.80
86 (30)	1.28 to 1.47
95 (35)	1.00 to 1.22
104 (40)	0.80 to 1.00
113 (45)	0.65 to 0.85
122 (50)	0.50 to 0.70
131 (55)	0.44 to 0.60
140 (60)	0.36 to 0.50



**Inspection
Procedure**
(Continued)

3. Inspect Air Duct Sensor.

A. Measure the sensor resistance according to the table and graph (specification).


NOTE:

- Even slightly touching the sensor may change the resistance value. Be sure to hold the connector of the sensor.
- When measuring, the sensor temperature must be the same as the ambient temperature.

HINT:


As the temperature increases, the resistance decreases.

TEMPERATURE °F (°C)	SPECIFICATION kΩ
50 (10)	9.48 to 10.49
59 (15)	7.50 to 8.28
68 (20)	5.95 to 6.57
77 (25)	4.77 to 5.25
86 (30)	3.85 to 4.21
95 (35)	3.12 to 3.40
104 (40)	2.53 to 2.79
113 (45)	2.06 to 2.30
122 (50)	1.69 to 1.91
131 (55)	1.39 to 1.59
140 (60)	1.15 to 1.33



**Inspection
Procedure
(Continued)**

4. Inspect Evaporator Temperature Sensor.



Select the appropriate graph (specification) using the following table.

NOTE:

Please inspect the sensors for model years not indicated by this bulletin, according to the instructions in the applicable repair manual.

MODEL	MODEL YEAR	COMMENTS	PART NUMBER	GRAPH
ES 300	1992 – 2001		88625-33070	2
ES 300/330	2002 – 2003		88625-17130	2
	2003		88625-33170	3
GS 300	1993 – 1997		88625-3A020	2
GS 300/400/430	1998 – 2002		88625-3A120	2
GX 470	2003 – 2005	Thermistor No. 1	88625-35050	3
		Thermistor No. 2	88625-16210	2
IS 300	2000 – 2001		88625-48010	2
LS 400	1990 – 1992		88625-32040	2
	1993 – 1994		88625-50100	2
	1995 – 2000		88625-50140	2
LS 430	2001 – 2005		88625-50160	2
LX 450	1996 – 1997		88625-60060	2
LX 470	1998 – 2000	Thermistor No. 2	88625-60140	2
	1998 – 2002	Thermistor No. 1	88625-60130	2
	2003 – 2005		88625-47011	2
RX 300	1998 – 2003		88625-48010	2
RX 330	2004	CBU	88625-48050	1
	2004 – 2005	CBU	88625-48060	3
		NAP		
SC 300/400	1991 – 2000		88625-32040	2

**Inspection
Procedure
(Continued)**

A. Measure the sensor resistance according to the selected graph (specification).

NOTE:


- Even slightly touching the sensor may change the resistance value. Be sure to hold the connector of the sensor.
- When measuring, the sensor temperature must be the same as the ambient temperature.

HINT:


As the temperature increases, the resistance decreases.

Graph 1:

TEMPERATURE °F (°C)	SPECIFICATION kΩ
14 (-10)	7.30 to 9.10
23 (-5)	5.65 to 6.95
32 (0)	4.40 to 5.35
41 (5)	3.40 to 4.15
50 (10)	2.70 to 3.25
59 (15)	2.14 to 2.58
68 (20)	1.71 to 2.05
77 (25)	1.38 to 1.64
86 (30)	1.11 to 1.32



Graph 2:

TEMPERATURE °F (°C)	SPECIFICATION kΩ
14 (-10)	7.40 to 9.20
23 (-5)	5.65 to 7.00
32 (0)	4.35 to 5.40
41 (5)	3.40 to 4.20
50 (10)	2.68 to 3.30
59 (15)	2.10 to 2.60
68 (20)	1.66 to 2.10
77 (25)	1.32 to 1.66
86 (30)	1.05 to 1.35



**Inspection
Procedure
(Continued)****Graph 3:**

TEMPERATURE °F (°C)	SPECIFICATION kΩ
14 (–10)	8.00 to 10.00
23 (–5)	6.15 to 7.65
32 (0)	4.75 to 5.85
41 (5)	3.70 to 4.55
50 (10)	2.91 to 3.55
59 (15)	2.32 to 2.80
68 (20)	1.85 to 2.22
77 (25)	1.48 to 1.77
86 (30)	1.20 to 1.43



**Inspection
Procedure
(Continued)**


5. Inspect Solar Sensor.

Four types of solar sensors are used on Lexus vehicles depending on the vehicle specifications. The inspection procedure for each type of sensor differs from the others. Select the appropriate inspection procedure from the table below according to vehicle specifications and perform the inspection.

EQUIPPED WITH AUTOMATIC LIGHT CONTROL SYSTEM	A/C SYSTEM WITH RIGHT/LEFT INDEPENDENT TEMPERATURE CONTROL	INSPECTION PROCEDURE
No	No	A
No	Yes	B
Yes	Yes	C
Yes	No	D

Procedure A:

- Disconnect the solar sensor connector.
- Measure the resistance between terminals 1 and 2 of the solar sensor under the following conditions:
 - Cover the sensor with a cloth to avoid direct light.
 - Expose the sensor to light from a distance of 300 mm (11.81 in.) or less with an inspection light.



NOTE:

- Terminal 1 of the sensor is always on the right, when the lock is facing up.
- When using an analog tester, connect the positive (+) lead to terminal 2 and negative (-) lead to terminal 1 of the solar sensor.

HINT:


If the light is weak, the sensor may not react. Be sure to use an incandescent light for an inspection light.

Standard:

CONDITION	SPECIFICATION
When the sensor is covered with a cloth (to avoid direct light)	Infinite ohms
When the sensor is exposed to light	Less than infinite resistance

**Inspection
Procedure
(Continued)****Procedure B:**

- a. Disconnect the solar sensor connector.
- b. Measure the resistance between terminals 2 and 3 of the solar sensor under the following conditions:
 - Cover the sensor with a cloth to avoid direct light.
 - Expose the sensor to light from a distance of 300 mm (11.81 in.) or less with an inspection light.

**NOTE:**

When using an analog tester, connect the positive (+) lead to terminal 3 and negative (-) lead to terminal 2 of the solar sensor.

HINT:

If the light is weak, the sensor may not react. Be sure to use an incandescent light for an inspection light.


Standard:

CONDITION	SPECIFICATION
When the sensor is covered with a cloth (to avoid direct light)	Infinite ohms
When the sensor is exposed to light	Less than infinite resistance

**Inspection
Procedure
(Continued)**

Procedure C:

- a. Turn the ignition switch ON.
- b. Measure the voltage between terminals TSR (+) and CLTE (–) of the connector under the following conditions:
 - Cover the sensor with a cloth to avoid direct light.
 - Expose the sensor to light from a distance of 300 mm (11.81 in.) or less with an inspection light.




HINT:

- If the light is weak, the sensor may not react. Be sure to use an incandescent light for an inspection light.
- Do not disconnect the solar sensor connector.

Standard:

CONDITION	SPECIFICATION
When the sensor is covered with a cloth (to avoid direct light)	Below 0.8 V
When the sensor is exposed to light	4.3 +/– 0.3 V

- c. Measure the voltage between terminals TSL (+) and CLTE (–) of the connector under the following conditions:
 - Cover the sensor with a cloth to avoid direct light.
 - Expose the sensor to light from a distance of 300 mm (11.81 in.) or less with an inspection light.



HINT:


- If the light is weak, the sensor may not react. Be sure to use an incandescent light for an inspection light.
- Do not disconnect the solar sensor connector.

Standard:

CONDITION	SPECIFICATION
When the sensor is covered with a cloth (to avoid direct light)	Below 0.8 V
When the sensor is exposed to light	4.3 +/– 0.3 V

**Inspection
Procedure
(Continued)****Procedure D:**

- a. Turn the ignition switch ON.
- b. Using the tester, measure the voltage between terminals TSD (+) and CLTE (-) of the connector under the following conditions:
 - Cover the sensor with a cloth to avoid direct light.
 - Expose the sensor to light from a distance of 300 mm (11.81 in.) or less with an inspection light.

**HINT:**

- If the light is weak, the sensor may not react. Be sure to use an incandescent light for an inspection light.
- Do not disconnect the solar sensor connector.

Standard:

CONDITION	SPECIFICATION
When the sensor is covered with a cloth (to avoid direct light)	Below 0.8 V
When the sensor is exposed to light	4.3 +/– 0.3 V

**Inspection
Procedure
(Continued)**

6. Inspect Room Humidity Sensor.

Measure the humidity and output voltage of the humidity sensor when the sensor is installed on the vehicle and the temperature at the humidity sensor position (room temperature sensor position) is 77°F (25°C).



If the output voltage is within the specifications according to the graph and table below, the sensor is normal.

HINT:

For the inspection procedure of the room temperature sensor, refer to “Room Temperature Sensor Inspection Procedure” in this bulletin.

- A. Turn the ignition switch to the ON position.
- B. Measure the voltage between terminal VO (3) and GND (2) of the room humidity sensor.
- C. Measure the humidity and voltage when the room temperature (humidity sensor position) is 77°F (25°C). According to the result, determine whether the sensor is normal or not.

HUMIDITY (% RH)	OUTPUT VOLTAGE AT 77°F (25°C)
10	0.70 to 1.08 V
20	0.72 to 1.57 V
30	1.13 to 1.95 V
40	1.61 to 2.24 V
50	1.99 to 2.46 V
60	2.26 to 2.66 V
70	2.48 to 2.85 V
80	2.68 to 3.04 V
90	2.87 to 3.05 V





**Technical Service
Information Bulletin**
July 13, 2005

Title:

WINDSHIELD WIPER BLADE MAINTENANCE AND CLEANING

Models:

'98 – '06 All Models

BODY

BO0004-05

Introduction The following procedures are recommended to maintain windshield wiper blade performance.

Applicable Vehicles • 1998 – 2006 model year **Lexus** vehicles.

Warranty Information	OP CODE	DESCRIPTION	TIME	OFP	T1	T2
	N/A	Not Applicable to Warranty	–	–	–	–

**Maintenance,
Cleaning
& Use**

Recommendations for Windshield Wiper Maintenance, Cleaning, and Use:

1. Scheduled Maintenance

- Check wiper rubber blades every 4 – 6 months or 7,500 miles for wear, cracking, and contamination.
- Clean glass and rubber wiper blades if blades are not clearing glass adequately. If this does not correct the problem, then replace the rubber elements.

2. Cleaning Procedure

- **Wiper Rubber:** Bugs, dirt, sap, and road grime on blades will cause streaking. Clean wiper rubber of road and environmental debris using cloth or paper towel soaked with windshield washer fluid or mild detergent.
- **DO NOT USE** fuel, kerosene, or petroleum based products to clean rubber wiper blades.
- **Windshield:** Bugs, sap, road grime, and car wash wax treatments decrease wiper performance.
- Rinse windshield with water and apply non-abrasive cleaner, such as Bon-Ami (www.faultless.com), with a sponge.

NOTE:

Make sure to use plenty of water with all powder based cleaners so the glass is not scratched.



Lexus Supports ASE Certification

**Maintenance,
Cleaning
& Use**
(Continued)

3. Contributors to Poor Performance/Decreased Rubber Blade Life (require rubber replacement)
 - Dusty areas cause the rubber edge to wear quickly.
 - Sand and salt used for road conditioning during winter causes the edge to wear quickly, so areas with significant snowfall require more frequent wiper replacement.
 - Heat and time cause the rubber to become excessively “permanent set,” so the rubber does not turn over, resulting in streaking and/or unwiped areas on the glass.
 - Rubber is easily cut or torn while using ice scrapers on the glass.
 - Rubber can be torn when pulling blades off a frozen windshield.
 - Using wipers instead of an ice scraper to remove frost and ice from the windshield during a car warm up can dull, nick, or tear the rubber.
 - Banging wiper on the glass to remove ice & snow can cause the blade to bend and rubber to come out of the blade providing the potential to scratch the glass.
 - Ice forms in wiper blade pin joints, which causes streaking and unwiped areas. To remove ice from pin joints, compress the blade and rubber with your hand to loosen the frozen joints. To prevent this condition, use winter blades with a rubber cover.



Technical Service Information Bulletin

September 29, 2004

Title:
SEAT BELT EXTENDER
Models:
'03 – '05 Model Year

BODY
REVISED
BO0009-04


TSIB REVISION NOTICE:

- December 9, 2005: The "Rear Seat Belt Extender Applications" section has been updated. In the Part Number Information table, the part numbers for series Q-6 have been updated.
- June 28, 2005: In the "Rear Seat Belt Extender Applications" section, the series number for the '05 ES 330 has been updated to R-7.

Previous versions of this TSIB should be discarded.

Introduction Lexus customers who find it necessary to increase the length of their seat belts may obtain Seat Belt Extenders at **no cost** through their local Lexus dealer.

- The extender is available in 6 inch, 9 inch, 12 inch, 15 inch, and 18 inch lengths.
- The extender is available **only in black**.
- Owners are informed of the Seat Belt Extender availability through the Lexus Owner's Manual included in each vehicle.



The customer (individual requiring the extender) must visit a Lexus dealership to have the required measurements made and to complete the Seat Belt Extender Worksheet. The worksheet will allow the proper fitting and selection of a Seat Belt Extender for the customer. The dealership personnel should then determine the applicable part number and place an order through **Dealer Daily**.

The dealership service department should complete the affixed Seat Belt Extender Customer Information Label on the part and review the "Owner Instruction Sheet" with the customer. The dealership should give a copy of the completed worksheet to the customer and keep the original in the customer's file.

To assure utmost owner satisfaction, it is recommended that a dealership designate one person to coordinate all activities related to the Seat Belt Extender issue.

It is recommended that dealerships **do NOT stock** Seat Belt Extenders due to the need for proper fitting to individual customers.

This bulletin contains the following information:

Procedure and Sample Label	Page 2
Application Charts	Page 3
Part Number Information	Page 4
Owner Instructions	Page 5
Seat Belt Extender Worksheet	Page 6

Applicable Vehicles

- 2003 – 2005 model year Lexus vehicles.

Warranty Information


OP CODE	DESCRIPTION	TIME	OPP	T1	T2
N/A	Not Applicable to Warranty	–	–	–	–



Lexus Supports ASE Certification

Procedure

1. Customer requests a Seat Belt Extender from dealer.
2. Dealer verifies the need for a Seat Belt Extender and obtains a current copy of this TSIB and copies the Worksheet.
3. Dealer measures the customer and completes the Worksheet. Dealer determines the correct part number and places an order for the part through Dealer Daily.
4. Dealer receives Seat Belt Extender and calls the customer to check the fit of the part.
5. If the Seat Belt Extender fit is good, dealership personnel completes the Customer Information Label on the part, explains usage of the part, and gives the customer a copy of the completed Worksheet.
6. Dealer places copy of the completed Worksheet in the customer's records.



Sample Seat Belt Extender Customer Information Label

CAUTION	
THIS SEAT BELT EXTENDER IS TO BE USED ONLY BY: _____	
ON VEHICLE: _____	
VIN: _____	
SEATING POSITION: _____	
USE BY OTHERS, OR IN ANOTHER SEATING POSITION, OR IN ANOTHER VEHICLE COULD REDUCE SEAT BELT RESTRAINT IN AN ACCIDENT AND RESULT IN PERSONAL INJURY.	

Front Seat
Belt Extender
Applications

FRONT SEAT – EXTENDER APPLICATION					
MODEL	TYPE	'05	'04	'03	
ES 300	All Models	–	–	R-5	
ES 330		R-6	R-6	–	
GS 300		R-3	R-3	R-3	
GS 430		R-3	R-3	R-3	
GX 470		K-6	K-6	K-6	
IS 300		K-6	K-6	K-6	
LS 430		R-3	R-3	R-3	
LX 470		K-6	K-6	K-6	
RX 300		–	–	R-5	
RX 330		R-7	R-7	–	
SC 430		R-3	R-3	R-3	

Rear Seat
Belt Extender
Applications

REAR SEAT – EXTENDER APPLICATION					
MODEL	TYPE	'05	'04	'03	
ES 300	All Models	–	–	R-5	
ES 330		R-7	R-5	–	
GS 300		K-5	K-5	K-5	
GS 430		K-5	K-5	K-5	
GX 470		K-5	K-5	K-5	
IS 300		R-5	R-5	R-5	
LS 430	RH, LH	R-3	R-3	R-3	
LX 470	All Models	K-5	K-5	K-5	
RX 300		–	–	R-5	
RX 330	RH, LH	R-6 or Q-5	R-6 or Q-5	–	
SC 430	All Models	R-5	R-5	R-5	

NOTE:

The extender must NOT be used for the center rear seat belt.

Part Number Information

SERIES	PART NUMBER PREFIX: 73399–				
	6 INCH	9 INCH	12 INCH	15 INCH	18 INCH
R-3	–50010	–50020	–50030	–50040	–50050
R-5	–16060	–16070	–16080	–16090	–16100
R-6	–35110	–35120	–35130	–35140	–35150
R-7	–48010	–48020	–48030	–48040	–48050
N-6	–20160	–20170	–20180	–20190	–20200
K-5	–35010	–35020	–35030	–35040	–35050
K-6	–35060	–35070	–35080	–35090	–35100
Q-5	–AE010	–AE020	–AE030	–AE040	–AE050
Q-6	–AE061	–AE071	–AE081	–AE091	–AE101

Owner Instructions Failure to follow the recommendations indicated below could result in reduced effectiveness of the seat belt restraint system in case of vehicle collision, causing personal injury.

If your seat belt cannot be fastened securely because it is not long enough, a personalized Seat Belt Extender is available from your Lexus dealer free of charge.


Please visit your local Lexus dealer so that the dealer can order the proper required length extender. Bring the heaviest coat you expect to wear for proper measurement and selection of length. Additional ordering information is available at your Lexus dealer.

When the Seat Belt Extender is provided for rear seat positions (with automatic locking retractor), make sure that the retractor is locked when in use.

To connect the extender to the seat belt, insert the tab into the seat belt buckle so that the buckle-release buttons of the extender and the seat belt are both facing outward as shown.

You will hear a click when the tab locks into the buckle.

When not in use, remove the extender and store in the vehicle for future use.



CAUTION:

On vehicles equipped with SRS – Occupant Classification System (OCS)*, it is critical that the extender tab be buckled into the buckle AFTER the occupant sits down in the seat.

Leaving extender installed in the buckle before sitting down will cause the OCS to be in the “airbag off” or disarmed state.

* OCS will enable or disable the passenger front and side airbags based on passenger weight and seat belt latch position classifying the passenger as a child or adult.

CAUTION:

When using the Seat Belt Extender, observe the following. Failure to follow these instructions could result in reduced effectiveness of the seat belt restraint system in case of vehicle accident, increasing the chance of personal injury.

- Never use the Seat Belt Extender if you can COMFORTABLY fasten the seat belt without it.
- The Seat Belt Extender must never be used with any child safety seats.
- Remember that the extender provided for you may not be safe when used on a different vehicle, for another person or for a different seating position than the one originally intended.

SEAT BELT EXTENDER WORKSHEET

PLEASE COPY THIS ORIGINAL WORKSHEET FOR EACH EXTENDER NEEDED

CAUTIONS:

- To minimize the chance and/or severity of injury in an accident, the Seat Belt Extender must only be used:
 - By the person for whom it was provided.
 - In the seat position for which it was provided.
- The Seat Belt Extender must never be used with any child safety seats.
- When the Seat Belt Extender is provided for rear seat positions (with automatic locking retractor), make sure the retractor is locked when extender belt is in use.

DEALER	SEAT BELT EXTENDER APPLICATION		APPLICANT		
DEALER CODE	DEALER NAME		APPLICANT NAME		
ADDRESS		ADDRESS			
CITY & STATE		ZIP	CITY & STATE	ZIP	PHONE
EMPLOYEE NAME	MODEL YEAR	BODY TYPE	SEATING POSITION	VEHICLE IDENTIFICATION NUMBER	

DIRECTIONS FOR DETERMINING PROPER EXTENDER LENGTH

- Place the seat in the position the applicant normally uses.
- With the applicant in the seat, wearing the thickest coat expected to be worn, pull belt all the way out and try to buckle belt.
 - If belt latches into buckle and feels comfortable against upper chest area, an extender is not needed.
 - If belt does not buckle, continue with Step 3.
 - If buckle latches but belt has no slack remaining, continue with Step 3.
- Measure distance between applicant's navel and seat belt buckle (Dimension A) and enter on Worksheet.
- With belt all the way out, measure distance between latch tip and buckle tip (Dimension B) and enter on Worksheet.

NOTE: If belt latches but there is no slack enter zero as Dimension B.

- Subtract Dimension B from Dimension A and record number in Check Number box on Worksheet.
- Seat Belt Extender length is Dimension B rounded up to next extender length (without exceeding Check Number).


NOTE: If extender length exceeds Check Number, an extender cannot be provided to the customer.

CAUTION:


On vehicles equipped with SRS — Occupant Classification System (OCS), it is critical that the extender tab be buckled into the buckle AFTER the occupant sits down in the seat.

Leaving extender installed in the buckle before sitting down will cause the OCS to be in the "airbag off" or disarmed state.

Dimension A:
NAVEL TO BUCKLE



Dimension B:
LATCH TO BUCKLE



SEAT BELT EXTENDER CALCULATION

DIMENSION A:

DIMENSION B:

CHECK NUMBER:

SEAT BELT EXTENDER AUTHORIZATION

- The same Seat Belt Extender can be used for right and left seating applications. Each Seat Belt Extender will have a label identifying the owner, VIN and seating position.*
- Applicant's Signature: _____ Date: _____
(Actual user of Seat Belt Extender)



**Technical Service
Information Bulletin**
November 9, 2005

Title:

**REAR BUCKLE EASE OF
USE IMPROVEMENT**

Models:

'05 ES 330

REVISED
TSIB
BODY
0011-05

TSIB REVISION NOTICE:

- November 10, 2005: The second Op Code has been updated in Warranty Information (Combo A for "Opposite Side").

Previous versions of this TSIB should be discarded.

Introduction The rear seat belt buckle tether strap has been modified to improve the ease of use for the customer.

Applicable Vehicles • **2005** model year **ES 330** vehicles produced **BEFORE** the Production Change Effective VINs shown below.

Production Change Information	MODEL	PART NAME	PART NUMBER	PRODUCTION CHANGE EFFECTIVE VIN
ES 330	Belt Assembly, RR Seat Inner w/ CTR, RH	73470-33040-A0	JTHBA30G955128105	
		73470-33040-B0	JTHBA30G455128366	
		73470-33040-C0	JTHBA30G855128774	
	Belt Assembly, RR Seat Inner w/ CTR, LH	73480-33130-A0	JTHBA30G955128220	
		73480-33130-B0	JTHBA30G755128247	
		73480-33130-C0	JTHBA30G755128409	

Parts Information	PREVIOUS PART NUMBER	CURRENT PART NUMBER	PART NAME	QTY
Same	73470-33040-A0	Belt Assembly, RR Seat Inner w/ CTR, RH	Belt Assembly, RR Seat Inner w/ CTR, RH	1
	73470-33040-B0			
	73470-33040-C0			
	73480-33130-A0	Belt Assembly, RR Seat Inner w/ CTR, LH	Belt Assembly, RR Seat Inner w/ CTR, LH	1
	73480-33130-B0			
	73480-33130-C0			

Warranty Information	OP CODE	DESCRIPTION	TIME	OPF	T1	T2
711511	R & R Rear Seat Belt Buckle	0.4	73470-33040-#0 73480-33130-#0	9A	99	
	Opposite Side	0.2				


Applicable Warranty*:

This repair is covered under the Lexus Powertrain Warranty. This warranty is in effect for 72 months or 70,000 miles, whichever occurs first, from the vehicle's in-service date.

* Warranty application is limited to correction of a problem based upon a customer's specific complaint.



Lexus Supports ASE Certification

Parts Identification**Repair Procedure****HINT:**

Use the same procedure for the LH side and RH side.

NOTE:

For removal of rear seat, refer to the Technical Information System (TIS), 2005 model year ES 330 Repair Manual: *Seat: Rear Seat Assy: Overhaul*.

1. Remove the rear seat cushion assembly.
2. Remove the rear seatback assembly.
3. Remove the rear door opening trim weatherstrip LH.
4. Remove the rear door opening trim weatherstrip RH.
5. Remove the roof side garnish inner LH.
6. Remove the roof side garnish inner RH.
7. Remove the center stop lamp assembly (without sun shade).
8. Remove the child restraint seat tether anchor cover.


**Repair
Procedure
(Continued)**

9. Remove the rear seat shoulder belt cover.

Using a screwdriver, disengage the 12 claws and remove the 3 rear seat shoulder belt covers.


HINT:

Tape the screwdriver tip before use.



10. Remove the package tray trim panel assembly.


A. Remove the 2 bolts and release the floor anchors of the seat belts.



**Repair
Procedure
(Continued)**


B. Without Sun Shade:

Disengage the 6 claws and 2 clips and remove the package tray trim panel assembly.



C. With Sun Shade:

Disengage the 2 clips and remove the package tray trim panel assembly.



11. Remove the rear seat center belt assembly RH.


Remove the bolt holding the retractor and disengage the claws of the stopper to remove the rear seat center belt assembly RH.

**Repair
Procedure
(Continued)**

12. Install the rear seat center belt assembly RH.

A. Check the degree of tilt when the ELR begins to lock.

Check that the belt does NOT lock at less than 15° of tilt in any direction but locks at over 45° of tilt when gently moving the installed retractor.



B. Install the retractor of the rear seat center belt assembly RH and torque the bolt.

Torque: 42 N·m (420 kgf·cm, 31 ft·lbf)

C. Check the ELR lock.

Check that the belt locks when pulled out quickly.

D. Check the fastening function for the child restraint system.

NOTE:

Check should be done with the assembly installed.

a. Check that the belt cannot be pulled out any more but can be rewound after being pulled out.

b. Check that the belt can be pulled out and rewound after being fully rewound.


**Repair
Procedure
(Continued)**

E. Install the floor anchor of the rear seat center belt assembly RH with the bolt facing the arrow mark on the plate toward the front of the vehicle.

Torque: 42 N•m (420 kgf•cm, 31 ft•lbf)

NOTE:

Ensure that the anchor does NOT run into any protrusions on the floor panel.



F. Check the ELR lock.

Check that the belt locks when pulled out quickly.

13. Remove the rear seat center belt assembly LH.


Remove the bolt and remove the rear seat center belt assembly LH.

**Repair
Procedure
(Continued)**

14. Install the rear seat center belt assembly LH.

A. Check the degree of tilt when the ELR begins to lock.

Check that the belt does NOT lock at less than 15° of tilt in any direction but locks at over 45° of tilt when gently moving the installed retractor.



B. Install the retractor of the rear seat center belt assembly LH and torque the bolt.

Torque: 42 N·m (420 kgf·cm, 31 ft·lbf)

C. Check the ELR lock.

Check that the belt locks when pulled out quickly.

D. Check the fastening function for the child restraint system.

NOTE:

Check should be done with the assembly installed.

a. Check that the belt cannot be pulled out any more but can be rewound after being pulled out.

b. Check that the belt can be pulled out and rewound after being fully rewound.


**Repair
Procedure
(Continued)**

E. Install the floor anchor of the rear seat center belt assembly LH with the bolt facing the arrow mark on the plate toward the front of the vehicle.

Torque: 42 N•m (420 kgf•cm, 31 ft•lbf)

NOTE:

Ensure that the anchor does NOT run into any protrusions on the floor panel.




F. Check the ELR lock.

Check that the belt locks when pulled out quickly.

15. Install the package tray trim panel assembly.

A. **Without Sun Shade:**


Engage the 6 claws and 2 clips to install the package tray trim panel assembly.



**Repair
Procedure
(Continued)**

B. With Sun Shade:

Engage the 2 clips to install the package tray trim panel assembly.



16. Reinstall the seat cushions in the reverse order of removal.
17. Dispose of the old seat belt appropriately. For proper disposal procedures, refer to TIS, 2005 model year ES 330 Repair Manual: *Seat Belt: Rear Seat Belt: Disposal*.




**Technical Service
Information Bulletin**
December 22, 2004

Title:
**CENTER CONSOLE
LATCH IMPROVEMENT**
Models:
'02 – '05 ES 300 & ES 330

BODY

BO012-04

Introduction For improved durability, the center console door lock opener for ES 300 and ES 330 vehicles are now made from metal, instead of the previous plastic material. This improved lock is available as a service part and will not require replacement of the entire console lid.



Applicable Vehicles • 2002 – 2005 model year **ES 300** and **ES 330** vehicles produced **BEFORE** the Production Change Effective VINs shown below.

**Production
Change
Information**

PLANT	PRODUCTION CHANGE EFFECTIVE VIN
Tsutsumi	JTHBA30G#50024455
Kanto	JTHBA30G#55077938

**Parts
Information**

PREVIOUS PART NUMBER	CURRENT PART NUMBER	PART NAME	QTY
58908-32050	58908-32020	Lock Assembly, Console Compartment Door	1

**Warranty
Information**

OP CODE	DESCRIPTION	TIME	OPP	T1	T2
BD4024	Replace Center Console Lock	0.2	58908-32050	62	12

Applicable Warranty*:

This repair is covered under the Lexus Comprehensive Warranty. This warranty is in effect for 48 months or 50,000 miles, whichever occurs first, from the vehicle's in-service date.

* Warranty application is limited to correction of a problem based upon a customer's specific complaint.



Lexus Supports ASE Certification

Page 1 of 1



**Technical Service
Information Bulletin**

November 10, 2005

Title:

**SEAT COVER REPLACEMENT FOR SIDE
AIRBAG EQUIPPED VEHICLES**

Models:

'97 – '06 All Lexus Models

BODY

BO012-05

TSIB UPDATE NOTICE:

The information contained in this TSIB supercedes TSIB No. BO004-98. TSIB No. BO004-98 is now obsolete and should be discarded.

Introduction Beginning in 1997, Lexus introduced side airbags for the LS 400. Starting with 1998, all Lexus vehicles are equipped with side airbags as standard equipment.

Lexus does **NOT** recommend replacement of original seat covers* with non-Lexus leather or other seat cover materials due to the following:

- Seat covers NOT recommended by Lexus may affect side airbag performance, in general or in part, during an accident.
- Modifications that negatively affect side airbag performance can result in severe occupant injuries.
- Seat covers are an integral part of this safety system. Replacing original seat covers* with non-Lexus leather or other seat cover materials may compromise the effectiveness of this safety system.
- The design of the seat is complex, integrating safety and strength with comfort and luxury.

***NOTE:**

Lexus original seat covers that were **NOT** designed for side airbag equipped seats cannot be used due to the effect on proper airbag performance.

Lexus strongly discourages modifying original equipment seats that have side airbags.

Additionally, Lexus strongly advises against the installation or use of aftermarket seat covers, which could impair the performance of the side airbags in the event of an accident.

Applicable Vehicles

- All 1997 – 2006 model year **Lexus** vehicles.

Warranty Information

OP CODE	DESCRIPTION	TIME	OPP	T1	T2
N/A	Not Applicable to Warranty	–	–	–	–



Lexus Supports ASE Certification



Technical Service Information Bulletin

February 16, 2005

Title:

M.I.L. "ON" DTC P0031, P0051, P2238, AND/OR P2241

Models:

'04 – '05 ES 330

ENGINE
EG003-05

Introduction Under certain driving conditions, some 2004 and 2005 model year ES 330 vehicles may exhibit a M.I.L. "ON" with at least one of the following DTCs:

- P0031 (Oxygen Sensor Heater Control Circuit Low [Bank 1, Sensor 1])
- P0051 (Oxygen Sensor Heater Control Circuit Low [Bank 2, Sensor 1])
- P2238 (Oxygen Sensor Pumping Current Circuit Low (for A/F Sensor) [Bank 1, Sensor 1])
- P2241 (Oxygen Sensor Pumping Current Circuit Low (for A/F Sensor) [Bank 2, Sensor 1])

The A/F sensor manufacturing process and the Engine Control Module (ECM) (SAE term: Powertrain Control Module/PCM) logic have been modified to improve these conditions.

NOTE:

- Version 12.01a or later Diagnostic Tester software is required to perform this procedure.
- Before proceeding, verify the ECM (PCM) calibration has NOT been updated by checking for the Authorized Modifications Label (shown in step 2 of the Repair Procedure).

**Applicable
Vehicles**

- 2004 model year **ES 330** vehicles.
- 2005 model year **ES 330** vehicles produced **BEFORE** the Production Change Effective VIN shown below.

**Production
Change
Information**

MODEL	PRODUCTION CHANGE EFFECTIVE VIN
2005 ES 330	JTHBA30G*55086805

**Warranty
Information**

OP CODE	DESCRIPTION	TIME	OPF	T1	T2
EG4029	Recalibrate ECM (PCM) Engine, R & R Both A/F Sensors	1.6	89661-33A40 89661-33A41 89661-33B30	8A	99

Applicable Warranty*:

This repair is covered under the Lexus Federal Emissions Warranty. This warranty is in effect for 96 months or 80,000 miles, whichever occurs first, from the vehicle's in-service date.

* Warranty application is limited to correction of a problem based upon a customer's specific complaint.



Lexus Supports ASE Certification

Parts Information

PREVIOUS PART NUMBER	CURRENT PART NUMBER	PART NAME	QTY
89467-33110	Same	Sensor, Air Fuel Ratio, Rear (Bank 1)	1
89467-33100	Same	Sensor, Air Fuel Ratio, Front (Bank 2)	1
N/A	00451-00001-LBL	Authorized Modifications Label	1

NOTE:

Authorized Modification Labels may be ordered in packages of 25 from the Materials Distribution Center (MDC) through Dealer Daily Dealer Support Materials System or by calling the MDC at 1-800-622-2033.

Required SSTs

SPECIAL SERVICE TOOLS (SSTs)	PART NUMBER	QUANTITY
Lexus Diagnostic Tester Kit*	01001270	1
12 Megabyte Diagnostic Tester Program Card with version 12.01a Software (or later)*	01002593-005	1

* Essential SSTs.

NOTE:

Additional Diagnostic Tester Kits, Program Cards, or other SSTs may be ordered by calling SPX/OTC at 1-800-933-8335.

Calibration Identification Chart

ENGINE	ECM (CPU)	PREVIOUS CALIBRATION ID	NEW CALIBRATION ID
3MZ-FE	Main	33350000 33350100 33360000	33360100
	Sub	53334000	53340000

NOTE:

- Although the calibration description in the Calibration Update Wizard and on the Diagnostic Tester reads "04 ES 330," these calibrations apply to 2004 and 2005 model year ES 330 vehicles produced before the Production Change Effective VIN shown on page 1 of this TSIB.
- 2004 model year ES 330 vehicles, which have been flash reprogrammed using the procedures in this TSIB, will contain upgraded 2005 model year OBD II logic. Refer to the 2005 model year ES 330 Repair Manual information on the Technical Information System (TIS) when checking Powertrain Diagnostic Trouble Codes (DTCs) on 2004 model year vehicles that have been reprogrammed.

**Repair
Procedure**

1. Replace both Bank 1, Sensor 1 and Bank 2, Sensor 1 air fuel ratio sensors.
2. Check for the Authorized Modifications Label affixed to the vehicle in the location shown in Figure 1. Confirm if ECM (PCM) calibration has been updated. If not the latest ECM (PCM) calibration — go to step 3.





Figure 1. Location of Authorized Modifications Label on 2004 ES 330

**Repair
Procedure**
(Continued)

3. Connect the Diagnostic Tester to the vehicle and select CURRENT ECU CAL from the ECU REPROGRAM MAIN MENU. Determine the vehicle's current ECU calibration (see Figure 2).
 - The sample screen prints seen below are the 12.01a software version and may differ from subsequent software versions.



NOTE:

- If Calibration ID matches “Previous Calibration ID” as shown in Calibration Identification Chart on page 2, proceed with flash reprogramming.
- If Calibration ID matches “New Calibration ID” as shown in Calibration Identification Chart, this vehicle has already been programmed. Refer to TIS for diagnostic procedures applicable to any stored DTCs.

4. If ECU calibration ID is not the same as the “New Calibration ID” listed previously, proceed to Flash Reprogram ECM (PCM).

5. Flash Reprogram ECM (PCM)

- A. Follow the procedures outlined in TSIB No. SS001–01, “*ECU Flash Reprogramming Process*,” and flash the ECM (PCM) with the new calibration file update.
- B. Enter the required information on the Authorized Modifications Label and affix it to the vehicle at the location shown in Figure 1 (page 3). The Authorized Modifications Label is available through the MDC, P/N 00451–00001–LBL.

6. Follow the procedures outlined in TSIB No. EG012–04, “*Entering VIN During ECM (PCM) Replacement and/or DTC P0630*,” and write the VIN to the ECM (PCM).
7. The repair is complete. Test drive vehicle to confirm normal operation.



Technical Service Information Bulletin

March 15, 2005

Title:
M.I.L. "ON" DTC P0346
Models:
'04 – '05 ES 330

ENGINE
EG006-05

Introduction Under certain driving conditions, some 2004 and 2005 model year ES 330 vehicles may exhibit a M.I.L. "ON" with the following DTC:

- P0346 (Camshaft Position Sensor "A" Circuit Range/Performance [Bank 2])

The Engine Control Module (ECM) (SAE term: Powertrain Control Module/PCM) logic have been modified to change this condition.

NOTE:

- Version 12.01a or later Diagnostic Tester software is required to perform this procedure.
- Before proceeding, verify the ECM (PCM) calibration has NOT been updated by checking for the Authorized Modifications Label (shown in step 1 of the Repair Procedure).

Applicable Vehicles

- 2004 model year **ES 330** vehicles.
- 2005 model year **ES 330** vehicles produced **BEFORE** the Production Change Effective VIN shown below.

Production Change Information	MODEL	PRODUCTION CHANGE EFFECTIVE VIN
	2005 ES 330	JTHBA30G*55086805

Warranty Information	OP CODE	DESCRIPTION	TIME	OFP	T1	T2
	EG5013	Recalibrate ECM (PCM) Engine	0.8	89661-33A40 89661-33A41 89661-33B30	8A	99

Applicable Warranty*:

This repair is covered under the Lexus Federal Emissions Warranty. This warranty is in effect for 96 months or 80,000 miles, whichever occurs first, from the vehicle's in-service date.

* Warranty application is limited to correction of a problem based upon a customer's specific complaint.



Lexus Supports ASE Certification

Parts Information

PREVIOUS PART NUMBER	CURRENT PART NUMBER	PART NAME	QTY
N/A	00451-00001-LBL	Authorized Modifications Label	1

NOTE:

Authorized Modification Labels may be ordered in packages of 25 from the Materials Distribution Center (MDC) through Dealer Daily Dealer Support Materials System or by calling the MDC at 1-800-622-2033.

Required SSTs

SPECIAL SERVICE TOOLS (SSTs)	PART NUMBER	QUANTITY
Lexus Diagnostic Tester Kit*	01001270	1
12 Megabyte Diagnostic Tester Program Card with version 12.01a Software (or later)*	01002593-005	1

* Essential SSTs.

NOTE:

Additional Diagnostic Tester Kits, Program Cards, or other SSTs may be ordered by calling SPX/OTC at 1-800-933-8335.


Calibration Identification Chart

ENGINE	ECM (CPU)	PREVIOUS CALIBRATION ID	NEW CALIBRATION ID
3MZ-FE	Main	33350000 33350100 33360000	33360100
	Sub	53334000	53340000

NOTE:


- Although the calibration description in the Calibration Update Wizard and on the Diagnostic Tester reads "04 ES 330," these calibrations apply to 2004 and 2005 model year ES 330 vehicles produced before the Production Change Effective VIN shown on page 1 of this TSIB.
- 2004 model year ES 330 vehicles, which have been flash reprogrammed using the procedures in this TSIB, will contain upgraded 2005 model year OBD II logic. Refer to the 2005 model year ES 330 Repair Manual information on the Technical Information System (TIS) when checking Powertrain Diagnostic Trouble Codes (DTCs) on 2004 model year vehicles that have been reprogrammed.

Repair Procedure 1. Check for the Authorized Modifications Label affixed to the vehicle in the location shown in Figure 1. Confirm if ECM (PCM) calibration has been updated. If not the latest ECM (PCM) calibration — go to step 2.



**Repair
Procedure**
(Continued)

2. Connect the Diagnostic Tester to the vehicle and select CURRENT ECU CAL from the ECU REPROGRAM MAIN MENU. Determine the vehicle's current ECU calibration (see Figure 2).
 - The sample screen prints seen below are the 12.01a software version and may differ from subsequent software versions.



NOTE:

- If Calibration ID matches “Previous Calibration ID” as shown in Calibration Identification Chart on page 2, proceed with flash reprogramming.
- If Calibration ID matches “New Calibration ID” as shown in Calibration Identification Chart, this vehicle has already been programmed. Refer to TIS for diagnostic procedures applicable to any stored DTCs.

3. If ECU calibration ID is not the same as the “New Calibration ID” listed previously, proceed to Flash Reprogram ECM (PCM).

4. Flash Reprogram ECM (PCM)

- A. Follow the procedures outlined in TSIB No. SS001–01, “*ECU Flash Reprogramming Process*,” and flash the ECM (PCM) with the new calibration file update.
- B. Enter the required information on the Authorized Modifications Label and affix it to the vehicle at the location shown in Figure 1 (page 3). The Authorized Modifications Label is available through the MDC, P/N 00451–00001–LBL.

5. Follow the procedures outlined in TSIB No. EG012–04, “*Entering VIN During ECM (PCM) Replacement and/or DTC P0630*,” and write the VIN to the ECM (PCM).
6. The repair is complete. Test drive vehicle to confirm normal operation.



**Technical Service
Information Bulletin**

March 28, 2005

Title:

RADIATOR CAP INSPECTION

Models:

All Models

TSIB

ENGINE


EG007-05

Introduction The procedure for inspecting the radiator cap has been revised. Please refer to the following procedures when inspecting the radiator cap on all Lexus models.

**Applicable
Vehicles**

- All Lexus models.

**Required
Equipment**

MANUFACTURER	EQUIPMENT	QTY
Snap-On/Sun SVTS262A (or equivalent)	Cooling System Tester (Radiator Cap Tester)	 1

NOTE:

Additional Lexus Approved Dealer Equipment may be ordered by calling Lexus Approved Dealer Equipment at 1-800-368-6787.

**Warranty
Information**

OP CODE	DESCRIPTION	TIME	OFP	T1	T2
N/A	Not Applicable to Warranty	—	—	—	—



Lexus Supports ASE Certification

Required SSTs

ITEM NO.	SPECIAL SERVICE TOOLS (SSTs)	PART NUMBER	QTY	DRW**	
1	Radiator Cap Test Set*		09230-00030-02	1	7
2	Radiator Cap Test Set (Small)*		09230-00020-02	1	7

* Essential SSTs.

** Refers to drawer number in SST Storage System.

NOTE:

Additional SSTs may be ordered by calling SPX/OTC at 1-800-933-8335.


Radiator Cap Identification Procedure

1. Use the illustration below to identify the vehicle's radiator cap type and kPa rating.
2. Proceed to the required inspection procedure for the radiator cap and kPa rating.


Radiator Cap Identification




N-Cap



Compact Cap



Plastic Cap





**Radiator Cap
Inspection
Procedure**
Type: N-cap, 88 kPa

1. Remove coolant and any foreign material on rubber points "A," "B," and "C."
2. Check that points "A," "B," and "C" are not deformed, cracked, or swollen.
3. Check that points "C" and "D" are not stuck together.
4. Apply engine coolant to points "B" and "C" before using the radiator cap tester.
 - Radiator Cap Tester:
Snap-On/Sun P/N SVTS262A
(or equivalent)
5. Before installing the radiator cap tester, use the applicable radiator cap adaptor provided in the following SST kits in conjunction with the radiator cap tester:
 - SST P/N 09230-00030-02
(09231-10080-01) or
09230-00020-02 (09231-10060-01)
6. When using the radiator cap tester, tilt it more than 30 degrees.
7. Pump the radiator cap tester several times, and check the maximum pressure.

Pumping speed: 1 pump/second

HINT:

Stop pumping when the valve opens and read the gauge. The gauge must be within the standard values listed below when the pressure valve opens. The cap is considered OK when the pressure holds steady or falls very slowly, but holds within the standard values listed below for one minute.


Specification:

VALVE OPENING PRESSURE	SPECIFIED CONDITION
Standard value (for brand-new cap)	74.0 to 103.0 kPa (0.75 to 1.05 kgf/cm ² , 10.7 to 14.9 psi)
Minimum standard value (for in-service cap)	59 kPa (0.60 kgf/cm ² , 8.53 psi)

If the maximum pressure is less than the minimum standard value, replace the radiator cap sub-assembly.

**Radiator Cap
Inspection
Procedure
(Continued)**

Type: N-cap, 108 kPa



1. Remove coolant and any foreign material on rubber points "A," "B," and "C."
2. Check that points "A," "B," and "C" are not deformed, cracked, or swollen.
3. Check that points "C" and "D" are not stuck together.
4. Apply engine coolant to points "B" and "C" before using the radiator cap tester.
 - Radiator Cap Tester:
Snap-On/Sun P/N SVTS262A
(or equivalent)
5. Before installing the radiator cap tester, use the applicable radiator cap adaptor provided in the following SST kits in conjunction with the radiator cap tester:
 - SST P/N 09230-00030-02
(09231-10080-01) or
09230-00020-02 (09231-10060-01)
6. When using the radiator cap tester, tilt it more than 30 degrees.
7. Pump the radiator cap tester several times, and check the maximum pressure.

Pumping speed: 1 pump/second

HINT:

Stop pumping when the valve opens and read the gauge. The gauge must be within the standard values listed below when the pressure valve opens. The cap is considered OK when the pressure holds steady or falls very slowly, but holds within the standard values listed below for one minute.

N-Cap: 108 kPa



Specification:

VALVE OPENING PRESSURE	SPECIFIED CONDITION
Standard value (for brand-new cap)	93.3 to 122.7 kPa (0.95 to 1.25 kgf/cm ² , 13.5 to 17.8 psi)
Minimum standard value (for in-service cap)	78.5 kPa (0.80 kgf/cm ² , 11.38 psi)

If the maximum pressure is less than the minimum standard value, replace the radiator cap sub-assembly.

**Radiator Cap
Inspection
Procedure
(Continued)**

Type: Compact Cap, 88 kPa



1. Remove coolant and any foreign material on rubber points "A," "B," and "C."
2. Check that points "A" and "B" are not deformed, cracked, or swollen.
3. Check that points "B" and "C" are not stuck together.
4. Apply engine coolant to point "B" before using the radiator cap tester.
 - Radiator Cap Tester:
Snap-On/Sun P/N SVTS262A
(or equivalent)
5. Before installing the radiator cap tester, use the applicable radiator cap adaptor provided in the following SST kits in conjunction with the radiator cap tester:
 - SST P/N 09230-00030-02
(09231-10080-01) or
09230-00020-02 (09231-10060-01)
6. When using the radiator cap tester, tilt it more than 30 degrees.
7. Pump the radiator cap tester several times, and check the maximum pressure.

Pumping speed: 1 pump/second

HINT:

Stop pumping when the valve opens and read the gauge. The gauge must be within the standard values listed below when the pressure valve opens. The cap is considered OK when the pressure holds steady or falls very slowly, but holds within the standard values listed below for one minute.

Compact Cap: 88 kPa



Specification:

VALVE OPENING PRESSURE	SPECIFIED CONDITION
Standard value (for brand-new cap)	74.0 to 103.0 kPa (0.75 to 1.05 kgf/cm ² , 10.7 to 14.9 psi)
Minimum standard value (for in-service cap)	59 kPa (0.60 kgf/cm ² , 8.53 psi)

If the maximum pressure is less than the minimum standard value, replace the radiator cap sub-assembly.

**Radiator Cap
Inspection
Procedure
(Continued)**

Type: Compact Cap, 108 kPa



1. Remove coolant and any foreign material on rubber points "A," "B," and "C."
2. Check that points "A" and "B" are not deformed, cracked, or swollen.
3. Check that points "B" and "C" are not stuck together.
4. Apply engine coolant to point "B" before using the radiator cap tester.
 - Radiator Cap Tester: Snap-On/Sun P/N SVTS262A (or equivalent)
5. Before installing the radiator cap tester, use the applicable radiator cap adaptor provided in the following SST kits in conjunction with the radiator cap tester:
 - SST P/N 09230-00030-02 (09231-10080-01) or 09230-00020-02 (09231-10060-01)
6. When using the radiator cap tester, tilt it more than 30 degrees.
7. Pump the radiator cap tester several times, and check the maximum pressure.

Pumping speed: 1 pump/second

HINT:

Stop pumping when the valve opens and read the gauge. The gauge must be within the standard values listed below when the pressure valve opens. The cap is considered OK when the pressure holds steady or falls very slowly, but holds within the standard values listed below for one minute.

Compact Cap: 108 kPa



Specification:

VALVE OPENING PRESSURE	SPECIFIED CONDITION
Standard value (for brand-new cap)	93.3 to 122.7 kPa (0.95 to 1.25 kgf/cm ² , 13.5 to 17.8 psi)
Minimum standard value (for in-service cap)	78.5 kPa (0.80 kgf/cm ² , 11.38 psi)

If the maximum pressure is less than the minimum standard value, replace the radiator cap sub-assembly.

**Radiator Cap
Inspection
Procedure
(Continued)**

Type: Plastic Cap, 108 kPa



1. Remove coolant and any foreign material on O-ring "A."
2. Check that O-ring "A" is not deformed, cracked, or swollen.
3. Apply engine coolant to O-ring "A" and rubber point "B" before using the radiator cap tester.
 - Radiator Cap Tester: Snap-On/Sun P/N SVTS262A (or equivalent)
4. Before installing the radiator cap tester, use the applicable radiator cap adaptor provided in the following SST kits in conjunction with the radiator cap tester:
 - SST P/N 09230-00030-02 (09231-10080-01) or 09230-00020-02 (09231-10060-01)
5. When using the radiator cap tester, tilt it more than 30 degrees.
6. Pump the radiator cap tester several times, and check the maximum pressure.

Pumping speed: 1 pump/second

HINT:

Stop pumping when the valve opens and read the gauge. The gauge must be within the standard values listed below when the pressure valve opens. The cap is considered OK when the pressure holds steady or falls very slowly, but holds within the standard values listed below for one minute.

Plastic Cap: 108 kPa



Specification:

VALVE OPENING PRESSURE	SPECIFIED CONDITION
Standard value (for brand-new cap)	93.3 to 122.7 kPa (0.95 to 1.25 kgf/cm ² , 13.5 to 17.8 psi)
Minimum standard value (for in-service cap)	78.5 kPa (0.80 kgf/cm ² , 11.38 psi)

If the maximum pressure is less than the minimum standard value, replace the radiator cap sub-assembly.



**Technical Service
Information Bulletin**
October 14, 2004

Title:

MAIN BEARING JOURNAL DIAMETER STAMPING LOCATION REVISION

Models:

'04 – '05 ES 330 & RX 330

ENGINE
EG011-04

Introduction The main bearing journal diameter stamp location has been changed on some 2004 and 2005 model year vehicles with 3MZ-FE engines. The stamping on the front of the block has been discontinued. Review this TSB for the stamping location.

Applicable Vehicles

- **2004 – 2005** model year **ES 330** and **RX 330** vehicles meeting the following specifications:
 - 3MZ-FE equipped vehicles with **engine serial numbers starting after 0138096**.

**Warranty
Information**


OP CODE	DESCRIPTION	TIME	OFP	T1	T2
N/A	Not Applicable to Warranty	–	–	–	–



Lexus Supports ASE Certification


Main Bearing Location**Cylinder Block Main Journal Bearing Diameter Location**

**Underside of Cylinder Block
(Contact Surface with Oil Pan No. 1)**



Front of Cylinder Block

**Previous Location
(Discontinued)**

**HINT:**

If replacing a bearing, replace it with one that has the same number. If the number of the bearing cannot be determined, select the correct bearing by adding together the numbers imprinted on the cylinder block and crankshaft, then refer to the table on the bottom of this page for the appropriate bearing number. The No. 1 and No. 4 journal bearings have 5 standard bearing sizes, marked 3, 4, 5, 6, and 7 accordingly. The No. 2 and No. 3 journal bearings have 5 standard bearing sizes, marked 1, 2, 3, 4, and 5 accordingly.



Technical Service Information Bulletin

October 14, 2004

Title:

ENTERING VIN DURING ECM (PCM) REPLACEMENT AND/OR DTC P0630

Models:

All '04 – '06 Models

REVISED
EG012-04
ENGINE

TSIB REVISION NOTICE:

- June 3, 2005: Content has been updated to include 2004 and 2006 model year vehicles. Step 4 of the VIN Write Procedure (page 2) and step 3 of the VIN Read Procedure (page 3) have been clarified to include RX 400h vehicles.

Previous versions of this TSIB should be discarded.

Introduction All 2005 and subsequent model year Lexus vehicles have the VIN (Vehicle Identification Number) stored in the Electronic Control Module (ECM) (SAE term: Powertrain Control Module/PCM) non-volatile memory. The VIN is accessible on the data stream using the Lexus Diagnostic Tester and can also be written to a new ECM (PCM) using a "VIN Read/Write" utility.

Service ECMs (supply parts) are shipped without the VIN; therefore, as part of the ECM (PCM) replacement procedure, the VIN must be written to the replacement ECM (PCM) using the Diagnostic Tester utility function. Failure to write the VIN to the ECM (PCM) will result in a M.I.L. "ON" condition and set DTC P0630: VIN Not Programmed or Mismatch – ECM (PCM).

It is very important to remember to enter the VIN on these vehicles. Vehicles with missing VINs are subject to failing some state and local vehicle emissions inspection and maintenance programs.

NOTE:

2004 model year vehicles which have been flash reprogrammed may contain updated 2005 model year OBD II logic. These vehicles will require VIN entry into the ECM (PCM) after reprogramming.

Applicable Vehicles

- 2004 model year vehicles that have been **flash reprogrammed**.
- All 2005 – 2006 model year vehicles.

Warranty Information

OP CODE	DESCRIPTION	TIME	OFP	T1	T2
N/A	Not Applicable to Warranty	–	–	–	–



Lexus Supports ASE Certification

Required SSTs	ITEM NO.	SPECIAL SERVICE TOOLS (SSTs)	PART NUMBER	QTY	DRW**	
	1	Lexus Diagnostic Tester Kit* NOTE: <ul style="list-style-type: none">• All components from this kit/set are required• 12 Megabyte Diagnostic Tester Program Card (P/N 01002593-005) with version 12.2a Software (or later) is required		LEX220036	1	8
	2	CAN Interface Module Kit* NOTE: <ul style="list-style-type: none">• All components from this kit/set are required		01002744	1	8

* Essential SSTs.

** Refers to drawer number in SST Storage System.

NOTE:

Additional Diagnostic Tester Kits, CAN Interface Modules, Program Cards, or other SSTs may be ordered by calling SPX/OTC at 1-800-933-8335.



VIN Write Procedure To write a VIN to a replacement ECM (PCM), use the following process:

1. Confirm the VIN. It is located on the front left of the instrument panel.
2. Connect the Diagnostic Tester to DLC3.
3. Turn the ignition switch and Diagnostic Tester switch ON.
4. **All vehicles except RX 400h:**
Select from the Diagnostic Tester menus: DIAGNOSIS, ENHANCED OBDII, VIN, and VIN WRITE.

RX 400h vehicles:

Select from the Diagnostic Tester menus: DIAGNOSIS, OBD/MOBD, HV ECU, VIN, and VIN WRITE.

5. Write the VIN in accordance with the Diagnostic Tester display.
6. Compare the VIN displayed on the Diagnostic Tester with the VIN on the instrument panel. If these are not the same, write the VIN again after turning the ignition switch OFF.




VIN Read Procedure

1. Connect the Diagnostic Tester to DLC3.
2. Turn the ignition switch and Diagnostic Tester switch ON.
3. **All vehicles except RX 400h:**
Select from the Diagnostic Tester menus: DIAGNOSIS, ENHANCED OBDII, VIN, and VIN READ.
RX 400h vehicles:
Select from the Diagnostic Tester menus: DIAGNOSIS, OBD/MOBD, HV ECU, VIN, and VIN READ.
4. Check the VIN displayed on the Diagnostic Tester.

HINT:

For further explanations, refer to the Technical Information System (TIS), appropriate model repair manual:
Diagnostics: SFI System: Registration.





Technical Service Information Bulletin

November 17, 2005

Title:

M.I.L. "ON" DTC P0171, P0174, P2195, OR P2197

Models:

'05 – '06 ES 330

ENGINE

EG019-05

Introduction Under certain driving conditions, some 2005 and 2006 model year ES 330 vehicles may exhibit a M.I.L. "ON" condition with at least one of the following DTCs:

- P0171 (System Too Lean [Bank 1])
- P0174 (System Too Lean [Bank 2])
- P2195 (Oxygen [A/F] Sensor Signal Stuck Lean [Bank 1, Sensor 1])
- P2197 (Oxygen [A/F] Sensor Signal Stuck Lean [Bank 2, Sensor 1])

The Air Fuel (A/F) sensor manufacturing process has been improved to correct this condition. The following repair procedures should be used to properly diagnose and repair the affected vehicles.

Applicable Vehicles • 2005 – 2006 model year **ES 330** vehicles produced **BEFORE** the Production Change Effective VIN shown below.

Production Change Information

MODEL	ENGINE	PRODUCTION CHANGE EFFECTIVE VIN
ES 330	3MZ-FE	JTHBA3#G#65148433

Parts Information

MODEL	ENGINE	PREVIOUS PART NUMBER	CURRENT PART NUMBER	PART NAME	QTY
ES 330	3MZ-FE	89467-33100	Same	Sensor, Air Fuel Ratio (Bank 1)	1
		89467-33110	Same	Sensor, Air Fuel Ratio (Bank 2)	1

Warranty Information

OP CODE	DESCRIPTION	TIME	OPP	T1	T2
895131	R & R A/F Sensor	0.6	89467-33100 89467-33110	8A	71

Applicable Warranty*:

This repair is covered under the Lexus Comprehensive Warranty. This warranty is in effect for 48 months or 50,000 miles, whichever occurs first, from the vehicle's in-service date.

* Warranty application is limited to correction of a problem based upon a customer's specific complaint.



Lexus Supports ASE Certification

Required SSTs	ITEM NO.	SPECIAL SERVICE TOOLS (SSTs)	PART NUMBER	QTY	DRW**	
	1	Lexus Diagnostic Tester Kit* NOTE: <ul style="list-style-type: none">• All components from this kit/set are required• 12 Megabyte Diagnostic Tester Program Card (P/N 01002593-005) with version 13.0a Software (or later) is required		LEX220036	1	8
	2	CAN Interface Module Kit* NOTE: <ul style="list-style-type: none">• All components from this kit/set are required		01002744	1	8

* Essential SSTs.

** Refers to drawer number in SST Storage System.

NOTE:

Additional Diagnostic Tester Kits, CAN Interface Modules, Program Cards, or other SSTs may be ordered by calling SPX/OTC at 1-800-933-8335.

Repair Procedure **DTC P0171 or P0174**

Refer to the Technical Information System (TIS), 2005 or 2006 model year ES 330 Repair Manual: *Diagnostics: SFI System (3MZ-FE): P0171, P0174*.

NOTE:

Only replace the A/F sensor indicated by the M.I.L. "ON" DTC(s).

DTC P2195 or P2197

Refer to TIS, 2005 or 2006 model year ES 330 Repair Manual: *Diagnostics: SFI System (3MZ-FE): P2195, P2197*.

NOTE:

Only replace the A/F sensor indicated by the M.I.L. "ON" DTC(s).



Technical Service Information Bulletin

February 22, 2005

Title:
PASSENGER AIRBAG INDICATOR LAMP
Models:
'04 – '05 ES 330 & RX 330

EL002-05
ELECTRICAL

Introduction The passenger airbag indicator lamp may switch from ON to OFF for front seat passengers weighing approximately less than 100 pounds, depending on their seating position. It is important for the front seat passengers to know that proper operation of the advanced frontal airbag system is highly dependent on the pressure placed on the seat bottom. Situations that add or subtract sensed weight can result in occupant misclassification. To minimize this situation:

- Check seating posture.
 - Passengers should be seated upright with their back against the seatback and feet on the floor.
- Check loading conditions.
 - Extra weight from items such as bags or groceries or toys hanging on the seatback can add to the sensed weight of the front seat passenger.
 - A rear seat passenger lifting the front seat with their legs, objects placed under the front seat, or the front seatback in contact with the rear seat can subtract from the sensed weight of the front seat passenger.

If the passenger airbag indicator lamp continues to switch ON to OFF after checking the above conditions, perform the following repair procedure.

NOTE:

The safest place for children is in the rear seat. Please note that Lexus recommends that you NEVER install a rear-facing child restraint in the front passenger seat, even if the passenger "Airbag OFF" lamp is illuminated. Please refer to the Owner's Manual for additional details.

Applicable Vehicles • 2004 – 2005 model year **ES 330** and **RX 330** vehicles produced **BEFORE** the Production Change Effective VINs shown on the following page.

Warranty Information

OP CODE	DESCRIPTION	TIME	OPP	T1	T2
EL4014	R & R Occupant Detection ECU	0.7	89952-33010 89952-48010	8A	74

Applicable Warranty*:

This repair is covered under the Lexus Comprehensive Warranty. This warranty is in effect for 48 months or 50,000 miles, whichever occurs first, from the vehicle's in-service date.

* Warranty application is limited to correction of a problem based upon a customer's specific complaint.



Lexus Supports ASE Certification

Production Change Information

MODEL	PLANT	DRIVETRAIN	PRODUCTION CHANGE EFFECTIVE VIN
ES 330	Tsutsumi	2WD	JTHBA30G#50024130
	Kanto		JTHBA30G#55068000
RX 330	TMK	2WD	JTJGA3#U#50046500
		4WD	JTJHA3#U#50076003
	TMMC	2WD	2T2GA3#U#5C021700
		4WD	2T2HA3#U#5C046800

Parts Information

PREVIOUS PART NUMBER	CURRENT PART NUMBER	PART NAME	QTY
89952-33010	89952-33011	Occupant Detection Computer	1
89952-48010	89952-48011		1

Required SSTs

SPECIAL SERVICE TOOLS (SSTs)	PART NUMBER	QUANTITY
Lexus Diagnostic Tester Kit*	01001270	1
12 Megabyte Diagnostic Tester Program Card with version 12.01a Software (or later)*	01002593-005	1
Occupant Seat Weight Set*	00002-09077-01	1

* Essential SSTs.

NOTE:

Additional Diagnostic Tester Kits, Program Cards, or other SSTs may be ordered by calling SPX/OTC at 1-800-933-8335.

Repair Procedure

1. Unfasten passenger seat and rock the assembly back providing access to the underside of the seat. For information to unfasten the passenger seat, refer to the Technical Information System (TIS): 2004 – 2005 model year ES 330 or RX 330 Repair Manual: *Seat: Front Seat Assembly LH: Overhaul*.
2. Disconnect the negative terminal of the vehicle battery.
3. Disconnect electrical connectors from Occupant Detection ECU.
4. Remove and replace the Occupant Detection ECU.
5. Reinstall the seat assembly. For more information, refer to TIS: 2004 – 2005 model year ES 330 or RX 330 Repair Manual: *Seat: Front Seat Assembly LH: Overhaul*.
Torque: 36.8 N·m (375 kgf·cm, 27 ft·lbf)
6. Reconnect the negative terminal of the vehicle battery.
7. Perform Zero Point Calibration and Sensitivity Check following prompts in the Diagnostic tool found under the Occupant Detect menu item (refer to TSIB No. EL007-03, “*Occupancy Classification System Calibration (DTC B1150 & B1650)*”.)
8. Reinitialize systems affected by the disconnection of the vehicle battery.



Technical Service Information Bulletin

January 31, 2003

Title:

PAINT STAINS UNDER RAPGARD™

Models:

'02 – '06 All Models

PA001-03
PAINT
REVISED


TSIB REVISION NOTICE:

- May 11, 2005: Applicable Vehicles has been updated to include 2004 – 2006 model years.

The previous TSIB should be discarded.

Introduction

On some vehicles, when Rapgard™ is removed, the paint may have a stained appearance under the clear coat. These stains should not be considered a defect in the paint (clear coat or color coat). Wrinkles in the Rapgard™ sometimes trap water and cause the paint to stain from the trapped moisture, especially on horizontal surfaces, such as the hood, roof, and trunk. Stains can be removed by heating the stained surface to remove the trapped moisture.



Applicable Vehicles

- 2002 – 2006 model year vehicles, **all models**.

Warranty Information

OP CODE	DESCRIPTION	TIME	OPP	T1	T2
BD1055	Remove Paint Stain Under Rapgard™	0.6	53301-#####	67	99

Applicable Warranty*:

This repair is covered under the Lexus Comprehensive Warranty. This warranty is in effect for 48 months or 50,000 miles, whichever occurs first, from the vehicle's in-service date.

* Warranty application is limited to correction of a problem based upon a customer's specific complaint.



Lexus Supports ASE Certification

Page 1 of 2

Required Tools & Material

TOOLS & MATERIALS	QUANTITY
Infrared Lamp or Heat Gun	1
Aluminum Foil or Damp Cloth	1
Thermometer	1

Repair Procedure

1. Use the aluminum foil or damp cloth to cover plastic/rubber parts that are near the stain.
2. Apply heat to the stain using an infrared lamp or heat gun.

NOTE:

Apply heat for 5 – 10 minutes at 158°F – 176°F (70°C – 80°C). Do NOT allow the surface to become hotter than 176°F (80°C). Measure the temperature with a thermometer.

3. After applying heat for 5 minutes, examine the area to determine if the stain has been removed. If the stain still exists, continue to apply heat and re-examine the stain 5 minutes later.



**Technical Service
Information Bulletin**
January 12, 2005

Title:

**IRON PARTICLE RUST
CONTAMINATION REPAIR**
Models:
'94 – Current

PAINT

PA001-05

Introduction The purpose of this bulletin is to provide information regarding the proper procedures to clean vehicles that may have been subjected to contamination by airborne iron particles such as rail dust.

Applicable Vehicles

- **1994 – Current** model year **Lexus** vehicles.

Required Tools & Materials

TOOLS & MATERIALS	QUANTITY
Auto Magic® Special Cleaner Concentrate™ #713*	1
Rubber Gloves, Aprons, Boots	
Eye Protection	
Sponges or Wash Mitts	As Needed
Pail or Bucket	

* Contact the main office of Auto Wax Company Inc. (1-800-826-0828 or www.automagic.biz) to find a local source for Auto Magic® Special Cleaner Concentrate.™

Condition During rail transportation or extended storage near industrial areas, vehicles may occasionally be subjected to contamination by airborne iron particles shed from railroad tracks, train wheels, exposure to heavy machinery facilities, grinding, welding, etc.

Inspection This type of contamination can be identified by the presence of small red or brown particles on the paint surface. These particles are often difficult to see on dark color paints, but can be easily felt when brushing a hand across horizontal body surfaces such as hood, roof, or deck lid.

CAUTION:

Because of the abrasiveness of these small iron particles, polishing or buffing procedures should not be attempted to repair the paint surface of an affected vehicle. This will result in further paint damage and detract from vehicle appearance.

Repair Washing the affected paint surfaces with Auto Magic® Special Cleaner Concentrate™ is the recommended method to dislodge embedded iron particles and remove the surrounding rust stains. The correct usage of Auto Magic® Special Cleaner Concentrate™ is described in this bulletin.

Warranty Information

OP CODE	DESCRIPTION	TIME	OPF	T1	T2
N/A	Not Applicable to Warranty	–	–	–	–



Lexus Supports ASE Certification

Page 1 of 2

General Precautions**WARNING:**

Auto Magic® Special Cleaner Concentrate™ is a corrosive material. Appropriate personal protection equipment must be worn to protect persons performing the contamination removal procedure. Please refer to the precautions on the product prior to use.

CAUTION:

Consult local or state regulations regarding the handling, use, and disposal of Auto Magic® Special Cleaner Concentrate™ prior to use.

Under no circumstances should contamination removal be performed in direct sunlight or contamination removal solution be allowed to dry on vehicle surfaces, as staining of plastic, rubber, or painted parts may result.

Repair Procedure

1. Move vehicle out of direct sunlight. Initially rinse with cool water then wash with liquid car wash detergent. Rinse again thoroughly with fresh water.
2. Dilute the mixture to a 1:8 ratio for painted surfaces. Use the recommended dilution ratio when applying to any other surface. Apply the diluted cleaner concentrate so that it evenly covers the affected area. Use an appropriate mitt or sponge to agitate the surface.
3. Thoroughly rinse vehicle with fresh water.
4. Inspect vehicle carefully both visually and by feel to determine if all iron particles have been removed. Repeat the wash several times if necessary to achieve complete removal.
5. Dry vehicle with a soft terry cloth towel and apply a non-abrasive, non-silicone glaze to obtain a high-gloss finish.



**Technical Service
Information Bulletin**
July 16, 2004

Title:

**WHEEL FILM FOR BRAKE ROTOR
RUST PREVENTION**

Models:

All Models with Wheel Film

PD001-04


PRE-DELIVERY SERVICE

Introduction To prevent brake rotor rust from forming during transportation and storage, wheel film will be adopted instead of using a cardboard type anti-rust cover.

The purpose of the wheel film is to protect the disc brake rotor from weather elements and initial rust before the vehicle is delivered to the customer. Consequently, the film should remain on the wheel as long as possible.

NOTE:

- Retain the wheel film on the disc wheel during vehicle display and storage.
- Do not remove the wheel film right away at Pre-Delivery Service (PDS) if the vehicle will be stored after PDS.
- Remove the wheel film just prior to delivery to customers.



Applicable Vehicles • All Models with wheel film.

Warranty Information


OP CODE	DESCRIPTION	TIME	OFP	T1	T2
N/A	Not Applicable to Warranty	-	-	-	-



Lexus Supports ASE Certification

Removal Procedure

Firmly hold the outer end of the wheel film to pull it off.

**NOTE:**

- If film adhesive residue is found on the disc wheel, remove it with a soft cloth dipped in ethyl alcohol (ethanol). Do not use thinner to remove the adhesive residue.
- When the wheel film is removed below an ambient temperature of 0°C (32°F), it is possible that the film may tear. For ease of film removal in cold conditions, please warm the film above 0°C (32°F) using one of the following methods:
 - Splash (hot) water on the wheel film.
 - Warm wheel film with cotton cloth soaked in hot water.
 - Warm wheel film with heat gun. Be sure not to overheat the film and wheel.
 - Warm wheel film by infrared heater (lamp) for paint. Be sure not to overheat the film and wheel.
 - Warm wheel film by steam car wash.
 - Park vehicle indoors (e.g. garage, etc.) for an extended period of time.

Disposal Procedure

Please follow local laws for disposal. Polyethylene film will not generate harmful gasses when it is burned.

Introduction Schedule

MODEL (FRONT & REAR)	PLANT	2003												2004											
		1	2	3	4	5	6	7	8	9	10	11	12	1	2	3	4	5	6	7	8	9	10	11	12
GS 430/300	JAPAN													Beginning January 2005											
GX 470														Beginning January 2005											
LX 470														Beginning January 2005											
RX 330	TMMC																								
	JAPAN																								
SC 430																									

This is a tentative schedule. There is a possibility that the introduction timing may be delayed on some models.



**Technical Service
Information Bulletin**
August 26, 2003

Title:

**PRE-DELIVERY SERVICE (PDS)
INFORMATION FOR ES 330**

Models:

'04 ES 330

PD002-03

PRE-DELIVERY SERVICE

Introduction The following items need to be performed during Pre-Delivery Service (PDS) on 2004 model year ES 330 vehicles.

Applicable Vehicles • 2004 model year **ES 330** vehicles.

Contents

ITEM NO.	SUBJECT	PAGE
1	D.C.C. Fuse Installation During PDS	2
2	Removal of Front Emergency Towing Eyelet and Installation of Towing Eyelet Hole Cover (Performed at Port)	3
3	Front License Plate Mounting Bracket Installation	4
4	Initialization of Moon Roof	5
5	Initial Calibration of Compass	6
6	Installation of Rubber Body Plugs	9

Warranty Information

OP CODE	DESCRIPTION	TIME	OPP	T1	T2
N/A	Not Applicable to Warranty	—	—	—	—




Lexus Supports ASE Certification

ITEM NO. 1: D.C.C. FUSE INSTALLATION DURING PDS

Introduction The D.C.C. fuse has been removed at the assembly plant to reduce parasitic current draw in transit and storage.

Installation Procedure The removed D.C.C. fuse (30 A) is stored in the blank space of the Junction Block in the engine compartment. The D.C.C. fuse must be reinstalled during Pre-Delivery Service (PDS) in the dealership as shown below.

**NOTE:**


- Removing the D.C.C. fuse cuts off power sources relating to the Dome, ECU-B and RAD No. 1 fuses.
- If the vehicle is stored in the dealership for a long period of time after PDS, disconnect the negative battery terminal to prevent battery discharge. Refer to TSIB PG009-02 for battery maintenance information.

ITEM NO. 2: REMOVAL OF FRONT EMERGENCY TOWING EYELET AND INSTALLATION OF TOWING EYELET HOLE COVER (PERFORMED AT PORT)**Installation Procedure**


1. Remove the emergency towing eyelet from the front bumper by turning counterclockwise.

NOTE:


If it is hard to loosen the emergency towing eyelet, use a steel bar.



2. Place the removed emergency towing eyelet in the tool tray in the luggage compartment.



3. Install the front towing eyelet hole cover which is stored in the glove box onto the front bumper as shown in the diagram.



ITEM NO. 3: FRONT LICENSE PLATE MOUNTING BRACKET INSTALLATION

Introduction The front license plate bracket and two self tapping screws are included in the luggage compartment.

Installation Procedure

1. Aligning the holes "A" of the mounting bracket with the dimples on the front bumper cover, mark the location of the holes "B" on the front bumper cover.

NOTE:

- Holes "A" are used for installation of the mounting bracket to the bumper cover.
- Holes "B" are used for installation of the front license plate to the mounting bracket.

2. Drill two relief holes with a diameter of 12 mm (0.47 in.) at the marks on the front bumper cover to prevent the license plate retaining bolt end from contacting the cover.

NOTE:

Do not drill the dimples on the front bumper cover.



3. Install the mounting bracket to the front bumper cover using the two self tapping screws.

Install the front license plate to the mounting bracket using bolts of the following dimensions:

Length: less than 25 mm (0.98 in.)

Diameter: 6.0 mm (0.24 in.)

Pitch: 1.0 mm (0.04 in.)



ITEM NO. 4: INITIALIZATION OF MOON ROOF


Introduction The moon roof is controlled by the sliding roof ECU which detects and memorizes the moon roof position by counting pulses of its motor from the fully tilt-up position as the start position. Once the battery terminal has been disconnected and reconnected, the sliding roof ECU does not detect and memorize the moon roof position, resulting in no functions of the “one-touch tilt up and down,” “one-touch slide open and close” and “jam protection.” Please initialize the moon roof position after reconnecting the battery terminal as outlined below.

Initialization Procedure

1. Turn the ignition switch to the “ON” position.
2. Push and hold the moon roof switch to the “TILT- UP” side until the moon roof tilts all the way up and then tilts down slightly (approximately 10 mm at rear end).
3. Check for proper operation of the “One-touch slide open and close” and “One-touch tilt up and down” functions by pushing the switch briefly to the “SLIDE OPEN” and “TILT UP” positions.

NOTE:

Jam protection function becomes effective through the above initialization procedure.




ITEM NO. 5: INITIAL CALIBRATION OF COMPASS

Introduction The compass indicates the direction that the vehicle is heading by detecting the direction and strength of the earth's magnetic field and processing this data using the compass sensor and microcomputer.

Detection of the direction and strength of the earth's magnetic field varies according to the area in which the vehicle is used and is affected by the residual magnetism of the vehicle. For this reason, the geographic direction displayed may also deviate from the direction determined by the earth's magnetic field according to the area in which the vehicle is used.

Therefore, please perform the initial calibration of the compass in your dealership prior to delivery to customers.




ITEM NO. 5: INITIAL CALIBRATION OF COMPASS (Continued)

Compass
Calibration
Procedure

- Turn the ignition switch to the "ON" position and check that the direction (N, NE, E, SE, S, SW, W, NW) appears on the compass display.



NOTE:

Pushing the "COMP" switch turns on or off the compass display.




- Push the "COMP" switch for approximately 3 seconds until the zone number (1 – 15) appears on the display. Then push the switch to select the number of the zone where the vehicle is located.

See the map below for zone reference.




ITEM NO. 5: INITIAL CALIBRATION OF COMPASS (Continued)**Compass
Calibration
Procedure
(Continued)**


3. Check that the direction appears several seconds after adjustment.
4. Start the engine and push the switch for about 6 seconds until "C" appears on the display.



5. Drive the vehicle slowly at 5 mph, or less, in a circle until the direction is displayed. If there is not enough space to drive in a circle, drive around the block until the direction is displayed.



After driving in circles 1 to 3 times, calibration is complete with the direction shown on the display.

**NOTE:**

- Do not perform calibration of the compass in a place where the earth's magnetic field is subject to interference by artificial magnetic fields (underground parking, under a steel tower, between buildings, roof parking, near a railroad crossing, near a large vehicle, etc.)
- During calibration, do not operate electric systems (moon roof, power windows, etc.) as they may interfere with the calibration.


ITEM NO. 6: INSTALLATION OF RUBBER BODY PLUGS

Introduction The ES 330 is provided with front and rear torque box holes to tie down the vehicle by wire or carrier truck transportation.

Installation Procedure Four (4) rubber body plugs are included in the glove compartment at the assembly plant. Install them into the two (2) front and two (2) rear torque box holes during Pre-Delivery Service (PDS).

NOTE:

If the rubber body plugs are not securely installed, road (tire) noise will transfer to the vehicle interior through the torque box holes and rust could occur inside the torque boxes by water entry.





**Technical Service
Information Bulletin**

February 11, 2005

Title:
**POWER SYSTEM INITIALIZATION
DURING PDS**
Models:
'05 All Lexus Models

PD010-05

PRE-DELIVERY SERVICE

Introduction The following is a list of the vehicle systems (Power Window, Sliding Roof, Tire Pressure Warning System, etc.) that need initialization during Pre-Delivery Service (PDS) and the TSIB numbers containing details on initializing each specific system.

NOTE:

Items in RED also need to be initialized any time the battery has been disconnected.

Applicable Vehicles

- All 2005 model year **Lexus** vehicles.

'05 MY Power System Initialization Table

MODEL NAME	INITIALIZATION SYSTEM ITEMS							
	COMPASS	POWER WINDOW	POWER BACK DOOR	SLIDING ROOF	TIRE PRESSURE WARNING SYSTEM		VGRS	SEAT
					DIRECT	INDIRECT		
ES 330	PD002-03	-	-	PD002-03	-	-	-	-
GS 430/300	PG007-00	-	-	-	-	-	-	-
GX 470	PG017-02		-	PG016-02	PD005-03	-	-	-
IS 300	PG022-01	-	-	-	-	-	-	-
LS 430	PG009-01	-	-	-	-	PD003-03	-	PG010-00
LX 470	PG007-00	-	-	-	-	-	PG011-02	-
RX 330	PD005-04	PD003-04	PD002-04	PD004-04	-	PD006-04	-	-
SC 430	PG010-01	-	-	-	PG006-01	-	-	PG005-03

Warranty Information

OP CODE	DESCRIPTION	TIME	OPP	T1	T2
N/A	Not Applicable to Warranty	-	-	-	-



Lexus Supports ASE Certification



Technical Service Information Bulletin

August 22, 2005

Title: **DCC FUSE INSTALLATION DURING PDS** Models: **'05 – '06 ES 330**

PD032-05


PRE-DELIVERY SERVICE

Introduction The DCC fuse has been removed at the assembly plant to reduce parasitic current draw in transit and storage.

Applicable Vehicles

- 2005 – 2006 model year **ES 330** vehicles.

Installation Procedure The removed DCC fuse (30A) is stored in the blank space of the Junction Block in the engine compartment. The DCC fuse must be reinstalled during Pre-Delivery Service (PDS) in the dealership as shown below.



NOTE:

- Removing the DCC fuse cuts off power sources relating to the DOME, ECU-B, and RAD No. 1 fuses.
- If the vehicle is stored in the dealership for a long period of time after PDS, disconnect the negative (–) battery terminal to prevent battery discharge. Refer to TSIB No. PG009-02, "Battery Maintenance for In-Stock Vehicles & Pre-Delivery," for battery maintenance information.

Warranty Information

OP CODE	DESCRIPTION	TIME	OPP	T1	T2
N/A	Not Applicable to Warranty	–	–	–	–



Lexus Supports ASE Certification

Page 1 of 1



Technical Service Information Bulletin

August 22, 2005

Title:

INITIALIZATION OF MOON ROOF DURING PDS

Models:

'05 – '06 ES 330

PD033-05

PRE-DELIVERY SERVICE

Introduction

The moon roof is controlled by the sliding roof ECU, which detects and memorizes the moon roof position by counting pulses of its motor from the fully "TILT-UP" position as the start position. Once the battery terminal has been disconnected and reconnected, the sliding roof ECU does not detect and memorize the moon roof position, resulting in no functions of the "one-touch tilt up and down," "one-touch slide open and close," and "jam protection." Initialize the moon roof position after reconnecting the battery terminal as outlined below.

NOTE:

Any time the battery terminal has been disconnected, initialize the moon roof after reconnecting the battery terminal.

Applicable Vehicles


- 2005 – 2006 model year **ES 330** vehicles.

Initialization Procedure

- Turn the ignition switch to the "ON" position.
- Push and hold the moon roof switch to the "TILT-UP" side until the moon roof tilts all the way up and then tilts down slightly (approximately 10 mm [0.39 in.] at rear end).
- Check for proper operation of the "one-touch slide open and close" and "one-touch tilt up and down" functions by pushing the switch briefly to the "SLIDE OPEN" and "TILT-UP" positions.

NOTE:

Jam protection function becomes effective through the above initialization procedure.



Warranty Information

OP CODE	DESCRIPTION	TIME	OPP	T1	T2
N/A	Not Applicable to Warranty	–	–	–	–



Lexus Supports ASE Certification

Page 1 of 1



**Technical Service
Information Bulletin**

August 22, 2005

Title:

**INITIAL CALIBRATION OF COMPASS
DURING PDS**

Models:

'05 – '06 ES 330


PD034-05

PRE-DELIVERY SERVICE

Introduction The compass indicates the direction that the vehicle is heading by detecting the direction and strength of the Earth's magnetic field and processing this data using the compass sensor and microcomputer.

Detection of the direction and strength of the Earth's magnetic field varies according to the area in which the vehicle is used and is affected by the residual magnetism of the vehicle. For this reason, the geographic direction displayed may also deviate from the direction determined by the Earth's magnetic field according to the area in which the vehicle is used.

Perform the initial calibration of the compass in your dealership prior to delivery to customers.



Applicable Vehicles

- 2005 – 2006 model year **ES 330** vehicles.

Warranty Information

OP CODE	DESCRIPTION	TIME	OFP	T1	T2
N/A	Not Applicable to Warranty	–	–	–	–




Lexus Supports ASE Certification

**Compass
Calibration
Procedure**

1. Turn the ignition switch to the “ON” position and check that the direction (N, NE, E, SE, S, SW, W, NW) appears on the compass display.



NOTE:

Pushing the “COMP” switch turns the compass display ON or OFF.




2. Push the “COMP” switch for approximately 3 seconds until the zone number (1 – 15) appears on the display. Then push the switch to select the number of the zone where the vehicle is located.

See the map below for zone reference.




**Compass
Calibration
Procedure
(Continued)**


3. Check that the direction appears several seconds after adjustment.
4. Start the engine and push the switch for about 6 seconds until "C" appears on the display.



5. Drive the vehicle slowly at 5 mph (8 km/h), or less, in a circle until the direction is displayed. If there is not enough space to drive in a circle, drive around the block until the direction is displayed.



After driving in 1 to 3 circles, calibration is complete with the direction shown on the display.



NOTE:

- Do NOT perform calibration of the compass in a place where the Earth's magnetic field is subject to interference by artificial magnetic fields (underground parking, under a steel tower, between buildings, roof parking, near a railroad crossing, near a large vehicle, etc.)
- During calibration, do NOT operate electric systems (moon roof, power windows, etc.) as they may interfere with the calibration.



Technical Service Information Bulletin

August 25, 2005

Title:

INSTALLATION OF RUBBER BODY PLUGS DURING PDS

Models:

'05 – '06 ES 330

PD035-05

PRE-DELIVERY SERVICE

Introduction The ES 330 is equipped with front and rear torque box holes to tie down the vehicle during transportation. Rubber body plugs need to be installed during Pre-Delivery Service (PDS).


Applicable Vehicles

- 2005 – 2006 model year **ES 330** vehicles.

Installation Procedure Four (4) rubber body plugs are included in the glove compartment at the assembly plant. Install them into the two (2) front and two (2) rear torque box holes located under the vehicle on both sides.

NOTE:

If the rubber body plugs are NOT securely installed, road (tire) noise will transfer to the vehicle interior through the torque box holes and rust could occur inside the torque boxes by water entry.



**Warranty
Information**

OP CODE	DESCRIPTION	TIME	OFP	T1	T2
N/A	Not Applicable to Warranty	–	–	–	–



Lexus Supports ASE Certification



**Technical Service
Information Bulletin**
August 25, 2005

Title:

**FRONT LICENSE PLATE MOUNTING
BRACKET INSTALLATION**

Models:

'05 – '06 ES 330

PD036-05

PRE-DELIVERY SERVICE

Introduction The ES 330 front license plate mounting bracket and two self-tapping screws are placed in the luggage compartment of the vehicle at the assembly plant. For states that require a front license plate, install the bracket and bolts on the bumper cover during Pre-Delivery Service (PDS) according to the following procedure.

Applicable Vehicles

- 2005 – 2006 model year **ES 330** vehicles.

Warranty Information

OP CODE	DESCRIPTION	TIME	OFP	T1	T2
N/A	Not Applicable to Warranty	–	–	–	–

Installation Procedure

1. Aligning the holes "A" of the mounting bracket with the dimples on the front bumper cover, mark the location of the holes "B" on the front bumper cover.


NOTE:

- Holes "A" are used for installation of the mounting bracket to the bumper cover.
- Holes "B" are used for installation of the front license plate to the mounting bracket.

2. Drill two relief holes with a diameter of 12 mm (0.47 in.) at the marks on the front bumper cover to prevent the license plate retaining bolt end from contacting the cover.

NOTE:


Do not drill the dimples on the front bumper cover.



Lexus Supports ASE Certification

**Installation
Procedure
(Continued)**

3. Install the mounting bracket to the front bumper cover using the two self-tapping screws.
4. Install the front license plate to the mounting bracket using bolts of the following dimensions:
Length: Less than 25 mm (0.98 in.)
Diameter: 6.0 mm (0.24 in.)
Pitch: 1.0 mm (0.04 in.)





**Technical Service
Information Bulletin**
August 26, 2005

Title:

FRONT EMERGENCY TOWING EYELET & EYELET HOLE COVER

Models:

'05 – '06 ES 330

PD037-05

PRE-DELIVERY SERVICE

Introduction The 2005 – 2006 model year ES 330 is shipped with a front emergency towing eyelet. Follow the procedure below to remove the eyelet and save for customer use.

Applicable Vehicles

- 2005 – 2006 model year **ES 330** vehicles.

Warranty Information


OP CODE	DESCRIPTION	TIME	OFP	T1	T2
N/A	Not Applicable to Warranty	–	–	–	–

Installation Procedure

1. Remove the emergency towing eyelet from the front bumper by turning counterclockwise.

NOTE:


If it is hard to loosen the emergency towing eyelet, use a steel bar.




Lexus Supports ASE Certification

**Installation
Procedure
(Continued)**

2. Place the emergency towing eyelet in the tool tray in the luggage compartment.



3. Install the front towing eyelet hole cover, which is stored in the glove box, onto the front bumper as shown in the illustration.





**Technical Service
Information Bulletin**

January 1, 1999

Title:

VOLUME 4 INFORMATION

Models:

All Models

TSIB


PG001-99

PRODUCT GENERAL INFORMATION

Introduction Lexus Technical Service Information Bulletins (TSIBs) continue to be one of the most current sources of technical information available. To ensure complete access to this reference source, use the following steps:

- Volume Four will begin with 1999 Technical Service Information Bulletins.
- Place this bulletin along with all 1999 TSIBs into the new binders received with this bulletin.
- Label this new binder "Volume Four" using the labels provided with the binder.
- Additional copies of 1994 through 1999 TSIBs are available to all Lexus Dealerships through the Non-Parts System (MDC NPM System) by using the following Part Number designation:

TSB Part Number Prefix



**Related TSIB
Part Numbers**

MATERIAL DESCRIPTION	PART NUMBER
1999 TSIB Binder complete with all bulletins issued to date	VOL4
New TSIB Binder and tabs only	00216-00001



Lexus Supports ASE Certification



Technical Service Information Bulletin

January 18, 2002

TSIB

Title: **REPLACEMENT CERTIFICATION LABELS**
Models: **All Models**

PG002-02

PRODUCT GENERAL INFORMATION

TSB UPDATE NOTICE:

The information contained in this TSIB updates PG015-01 dated May 4, 2001.
Revised text is **red** and **underlined**. The changes will take place February 1, 2002.

Introduction

Replacement Certification Labels (vinyl label affixed to driver's door or door post) **may be** available from Lexus providing the request meets one of the criteria listed below.

Certification Label Location



MFD.BY:TOYOTA MOTOR CORPORATION DATE 10/01
GVWR: 2247KG (3040LB)
GAWR: FRT 1379KG (3040LB) WITH P225/70R16 TIRES
16X6 1/2JJ RIMS AT 210 KPA (30PSI) COLD
RR 1153KG (2540LB) WITH P225/70R16 TIRES.
16X6 1/2JJ RIMS AT 210 KPA (30PSI) COLD
THIS VEHICLE CONFORMS TO ALL APPLICABLE
FEDERAL MOTOR VEHICLE SAFETY, BUMPER, AND
THEFT PREVENTION STANDARDS IN EFFECT ON
THE DATE OF MANUFACTURE SHOWN ABOVE.
JTOXX00X0X0000000 MPV MCU10L-AWPGKA
C/TR 8P4/LB00
A/AM-01A/
U140E
MADE IN JAPAN
NO. 736



Applicable Vehicles

- All Lexus vehicles.

Certification Label Criteria

1. The vehicle is in an accident and the label is damaged or is attached to a part that will be replaced during the repair.

NOTE:

- Processing a new label **will be delayed significantly if the original certification label is not available.**
- A replacement label **MAY NOT be available if the vehicle is more than 5 years old and the old label does not accompany this request.**

2. The label is stolen.

Procurement Procedure

To request a replacement label, complete a copy of the form on the back of this bulletin. Your dealer parts account will be billed **\$25.00** for each replacement of a damaged or stolen label.

NOTE:

All replacement labels for damaged and/or stolen vehicles are subject to approval by the Technical Compliance Department. If you have any specific questions, contact (310) 468-3390.

Warranty Information


OP CODE	DESCRIPTION	TIME	OPN	T1	T2
N/A	Not Applicable to Warranty	—	—	—	—



Lexus Supports ASE Certification



APPLICATION FOR REPLACEMENT CERTIFICATION LABEL



REASON FOR REPLACEMENT

- ACCIDENT DAMAGE
- STOLEN
- OTHER _____

REASON/EXPLANATION

PLEASE PROVIDE CORRECT VIN



ATTACH ORIGINAL LABEL HERE

NOTE:

Original label **MUST** accompany this application or order will be significantly delayed.

DEALER INFORMATION

DEALER CODE:

DEALER NAME:

ADDRESS:

STREET ADDRESS

CITY, STATE, ZIP CODE

TELEPHONE:

()

AREA CODE, TELEPHONE NUMBER

CONTACT:

FIRST NAME, LAST NAME

MAIL (DO NOT FAX) THE COMPLETED REQUEST FORM WITH THE OLD LABEL TO:

TOYOTA MOTOR SALES, U.S.A. INC.
TECHNICAL COMPLIANCE DEPARTMENT, S207
19001 S. WESTERN AVENUE
TORRANCE, CA 90509-2991



**Technical Service
Information Bulletin**
March 2, 2005

Title:

**TIRE POSITIONING BEFORE NEW
VEHICLE DELIVERY**

Models:

'05 – '06 All Lexus

PRODUCT GENERAL INFORMATION
PG002-05

Introduction During the manufacturing process, tire characteristics are measured. Tires are then mounted on the vehicle as matched sets to help reduce conditions such as pulling or drifting. If the wheels are replaced or refinished before vehicle delivery, it is important that the tires remain on the vehicle in the same location and in the same direction of rotation.

Please refer to the following procedure to ensure that the original tires stay in the same location on the vehicle.

Applicable Vehicles

- All 2005 – 2006 model year Lexus vehicles.

Installation Procedure

1. Mark the tire installation position on the inward facing tire sidewall.
Example: Front Right = FR, Front Left = FL, Rear Right = RR, Rear Left = RL
2. Install the original tires on the new or refinished wheels with the marked side facing inwards.
3. Place the tire/wheel assemblies on the vehicle in the marked positions.

NOTE:

Torque the wheel nuts to the proper torque value in sequence.

Warranty Information

OP CODE	DESCRIPTION	TIME	OFP	T1	T2
N/A	Not Applicable to Warranty	–	–	–	–



Lexus Supports ASE Certification



Technical Service Information Bulletin

January 18, 2002

Title:
REPLACEMENT VIN PLATES
Models:
All Models

PG003-02


PRODUCT GENERAL INFORMATION

TSB UPDATE NOTICE:

The information contained in this TSIB updates PG016-01 dated May 4, 2001.
Revised text is **red** and **underlined**. The changes will take place February 1, 2002.

Introduction

Replacement **VIN** plates (metal plates riveted to dashboard) **may be** available from Lexus providing the request meets the criteria listed below.



VIN Plate Location

Applicable Vehicles

- All Lexus vehicles.

Replacement VIN Plate Criteria

NOTE:

The original plate to be replaced MUST accompany the request.

NOTE:

If a plate is stolen, be sure to contact the State Police or your State's Department of Motor Vehicles (DMV). In most cases the State DMV will issue a unique number so that the original number can be included on stolen vehicle listings. If this is the case, a replacement plate is NOT available from Lexus. However, the original VIN, NOT the state issued VIN, must be used on all warranty claims.

Procurement Procedure

To request a replacement plate, complete a copy of the form on the back of this page. Note that the damaged VIN plate **MUST** accompany the request form. Your dealer parts account will be billed **\$25.00** for each replacement of a damaged plate.

NOTE:

All replacement plates for damaged and/or stolen vehicles are subject to approval by the Technical Compliance Department. If you have any specific questions, contact **(310) 468-3390**.

Warranty Information

OP CODE	DESCRIPTION	TIME	OPN	T1	T2
N/A	Not Applicable to Warranty	—	—	—	—




Lexus Supports ASE Certification



APPLICATION FOR REPLACEMENT VIN PLATE

JT0XX00X0X0000000



REASON FOR REPLACEMENT

ACCIDENT DAMAGE

OTHER _____

REASON/EXPLANATION

PLEASE PROVIDE CORRECT VIN

ATTACH DAMAGED PLATE HERE

DEALER INFORMATION

DEALER CODE:

DEALER NAME:

ADDRESS:

STREET ADDRESS

CITY, STATE, ZIP CODE

TELEPHONE:

()

AREA CODE, TELEPHONE NUMBER

CONTACT:

FIRST NAME, LAST NAME

MAIL (DO NOT FAX) THE COMPLETED REQUEST FORM WITH THE OLD PLATE TO:

TOYOTA MOTOR SALES, U.S.A. INC.
TECHNICAL COMPLIANCE DEPARTMENT, S207
19001 S. WESTERN AVENUE
TORRANCE, CA. 90509-2991



**Technical Service
Information Bulletin**
September 12, 2002

Title:

**BATTERY MAINTENANCE FOR
IN-STOCK VEHICLES & PRE-DELIVERY**
Models:
All Models & Model Years Through Current

PG009-02

PRODUCT GENERAL INFORMATION

Introduction A battery in a stored vehicle is subject to conditions that can reduce its performance and life. These conditions include storage period, temperature, parasitic drain, and battery load. Because of these factors, battery inspection and maintenance are required in order to ensure proper operation and optimal battery life.

As a matter of policy, Lexus does not provide battery warranty coverage for discharged and/or failed batteries due to lack of maintenance; it is the dealer's responsibility to maintain the specified state of charge of the vehicle's battery while in stock and assure proper state of charge at delivery.

To eliminate customer service concerns due to an undercharged battery during the first few weeks of ownership, **all dealers should check battery state of charge and recharge, if necessary, just prior to delivery** (i.e., within 48 hours of delivery).

This new procedure will improve the new vehicle ownership experience by greatly reducing the risk of having a low performance battery concern due to extended storage periods and/or short engine run times prior to the vehicle sale.

Applicable Vehicles • All models and model years through current.

Required Tools & Material

	SPECIAL SERVICE TOOLS (SSTs)	MANUFACTURER	PART NUMBER
MICROPRO 815 Digital Battery Analyzer (Essential SST)*		Midtronics	00002-MP815-T

* This SST can be ordered through SPX/OTC by calling 1-800-933-8335.

NOTE:

MICROPRO 815 Digital Battery Analyzer should be periodically updated through the Technical Information System (TIS) for new vehicle models. For detailed information, please see TSIB SS002-02, "Midtronics Battery Tester Software Update."

Warranty Information

OP CODE	DESCRIPTION	TIME	OFP	T1	T2
N/A	Not Applicable to Warranty	—	—	—	—



Lexus Supports ASE Certification

Recommended Equipment

TOOLS & EQUIPMENT	MANUFACTURER	PART NUMBER
Fast Battery Charger**	Associated	ASE6003
Fast Battery Charger**	Christie	CAPPDQ

** These tools can be ordered through the Lexus Approved Dealer Equipment program by calling 1-800-368-6787.

NOTE:

The “Fast Battery Chargers” listed above have been tested and approved by Lexus. These state-of-the-art “smart” chargers were designed to charge batteries at an accelerated rate, without the possibility of damage. Using non-microprocessor controlled battery chargers for fast charging purposes can damage the battery.


Inspection Procedure

All vehicles are to be inspected according to the procedures listed below using the MICROPRO 815 battery tester no more than 48 hours prior to customer vehicle delivery.

PRIOR TO TESTING:

If necessary, remove battery surface charge by turning on high beam headlights for 60 seconds, then let battery voltage recover for one minute.

1. Connect test clamps to battery. (Display will show four zeros indicating a good connection).
2. For cold battery (<32°F) or after charge test, press TEST MODE key until appropriate test is selected.



3. Input battery stock number.

NOTE:

Stock number must be used for warranty cases because you cannot read the warranty code if CCA/CA rating is input.


4. Press STK#/Code key to start test.

NOTE:

Stock numbers are listed on the reference card located in the tester's cover. Stock numbers can also be referenced on TIS. The TIS listings will always have up-to-date information.


Stock number location in TIS:

1. Go to TIS Home Page.
2. Click on “Diagnostics.”
3. Click on “Midtronics Battery Tester Software.”
4. Click on “Stock Number Chart.”



Inspection Procedure (Continued)

5. Read STATE OF CHARGE and BATTERY CONDITION.
 - a. If battery is at 75% STATE OF CHARGE or greater, release vehicle to new owner.
 - b. If battery is less than 75% STATE OF CHARGE proceed to Battery Service Procedure.



Battery Service Procedure

Follow the procedures below according to the BATTERY CONDITION results.

BATTERY CONDITION: "Good return to service" (less than 75% State of Charge)

CHARGE BATTERY — Do not attempt to service (use) when 10% State of Charge. Charge battery using one of the recommended chargers indicated above (or equivalent) following the Quick Charge instructions accompanying that machine.

BATTERY CONDITION: “Charge and return to service”

Charge battery using one of the recommended chargers indicated above (or equivalent) following the Quick Charge instructions accompanying that machine.

BATTERY CONDITION: "Charge and retest"

The battery must be Quick Charged and retested using the **After charge** test mode. Carry out the service according to the result of the retest.

BATTERY CONDITION: "Replace"

The battery must be replaced. Press the STK#/CODE key to show the warranty code for the repair order and for the Warranty Battery Label.

Battery Replacement

If a vehicle battery needs to be replaced for a warrantable condition, make sure to complete a Warranty Battery Label and affix it to the failed battery for proper warranty parts and claim processing.

Please include the Vehicle Identification Number and warranty code on the Warranty Battery Label.

WARRANTY BATTERY LABEL ETIQUETA PARA BATERIA DE GARANTIA (Please Print / Líñese con Letra de Molde Por Favor)		
<hr/> <hr/> <hr/> <hr/> <hr/>		
Dealer Code Código de Agencia		
<hr/> <hr/>		
Vehicle Identification Number (VIN) Número de Identificación de Vehículo (NIV)		
<hr/> <hr/>		
Repair Order No. No. de Orden de Reparación	Repair Date Fecha de Reparación	Failure Code Código de Falla
<hr/> <hr/>		
Veh. Date of First Use Fecha de Primer Uso del Veh.	Original Install Date Fecha de Instalación Original (Svc. part replacement only/ solamente para el reemplazo de partes de servicio)	Battery Mos. In Svc. Número de meses que Batería está en servicio
<hr/> <hr/>		
08/02	00404-BTTRY-LABEL	

**Recommended
Battery
Maintenance**

In addition to this new pre-delivery battery test, a **monthly battery inspection** is still required for stored vehicles. If your dealership is located in an area subject to extreme temperatures (hot or cold), periodic maintenance may need to be performed more frequently.

To reduce parasitic battery drain for vehicles in storage for one week or more, the negative battery cable should always be disconnected to reduce battery discharge. When the negative battery cable is reconnected, please check and reset electrical components such as the clock, radio, etc.

NOTE:

For your reference, the electrical system is made inoperative by removing the appropriate fuse indicated in the Electrical Wiring Diagram.



**Technical Service
Information Bulletin**

March 11, 2005

Title:

**FAILURE TO INITIALIZE CAN
INTERFACE MODULE**

Models:

'04 – '05 Applicable Models

TSIB
REVISED
SS001-05
SPECIAL SERVICE TOOLS

TSIB REVISION NOTICE:

- June 23, 2005: The “Required SSTs” section has been updated.
The previous TSIB should be discarded.

Introduction If the Diagnostic Tester fails to initialize CAN-based communication with on-board vehicle controllers, a damaged cable or inoperative CAN Interface Module may be at fault. This bulletin provides test procedures to check the integrity of the Diagnostic Tester cables and the CAN Interface Module.

Applicable Vehicles • 2004 – 2005 model year **CAN-equipped** vehicles including 2004 model year LS 430 and 2005 model year GX 470 and LS 430.

Warranty Information

OP CODE	DESCRIPTION	TIME	OFP	T1	T2
N/A	Not Applicable to Warranty	–	–	–	–



Lexus Supports ASE Certification

Required SSTs	ITEM NO.	SPECIAL SERVICE TOOLS (SSTs)	PART NUMBER	QTY	DRW**	
	1	Diagnostic Tool Set*	LEX220036	1	8	
COMPONENT(S) OF KIT/SET		Four (4) components from this kit/set are required: <ul style="list-style-type: none"> Tester (P/N 02002019) 12 Megabyte Program Card Kit (P/N 01002593-005) with version 12.2a Software (or later) 14/26 Pin DLC Cable (P/N 02001637) 14 Pin DLC Self Test Adapter (P/N 02001607) 				
	2	CAN Module Kit*	01002744	1	8	
COMPONENT(S) OF KIT/SET		NOTE: <ul style="list-style-type: none"> All components from this kit/set are required Module box cannot be ordered separately J1962 OBD2-II (CAN DLC) (P/N 02003180) 				

* Essential SSTs.

** Refers to drawer number in SST Storage System.

NOTE:


Additional Diagnostic Tool Sets, CAN Module Kits, Program Cards, or other SSTs may be ordered by calling SPX/OTC at 1-800-933-8335.

Diagnostic Procedure Failure to initialize CAN-based communications between the Diagnostic Tester and on-board vehicle controllers can be caused by the following issues:

- The 14/26 Pin DLC cable is damaged, causing an open communication circuit.
- The DLC cable is damaged, causing an open communication circuit.
- The CAN Interface Module is damaged.
- The vehicle's CAN Communication System has a fault, requiring further vehicle diagnostics.

NOTE:

The Diagnostic Tester may operate properly in other modes such as OBD/MOBD and CARB OBDII with a damaged cable or CAN module.

Figure 1**NOTE:**

To lengthen the Diagnostic Tester cable life, do not wrap the cable around the tester, or hold the tester only by the cable.


**Diagnostic
Procedure
(Continued)**

To determine the cause of communication error, perform the following steps:

1. Using the Diagnostic Tester, perform the CAN MODULE VERSION self test. Select DIAGNOSIS/SETUP/SELF TEST and perform the following screen flow.

NOTE:

Before performing test, confirm that the Diagnostic Tester, 14/26 Pin DLC cable, and CAN Interface Module are all securely connected.

Figure 2**SELF TEST Result:**

SELF TEST FAILED: CAN VIM did not respond. Go to step 2.


SELF TEST PASSED: Go to step 3.

This response verifies the CAN module and the 14/26 Pin DLC cable are OK.


**Diagnostic
Procedure
(Continued)**

2. Perform the Data Link Self Test (Figure 3).

Figure 3




DATA LINK SELF TEST Result:



**Diagnostic
Procedure
(Continued)**

3. Inspect the J1962 OBD2-II cable (CAN DLC).
 - A. Disconnect the CAN Interface Module from the J1962 OBD2-II cable (CAN DLC).
A small Phillips screwdriver is required to separate the CAN Interface Module from the J1962 OBD2-II cable.
 - B. Test the J1962 OBD2-II cable (CAN DLC) for continuity.

**J1962 OBD2-II Cable (CAN DLC) Test Result:**

(More than 6 Ω)
Replace the J1962 OBD2-II cable
(CAN DLC, P/N 02003180).

Suspect vehicle side problem.

Refer to the Technical Information System (TIS): applicable model year Repair Manual: *Diagnostics: CAN Communication System: Problem Symptoms Table: Check CAN Bus Line.*

NOTE:

If the Diagnostic Tester successfully communicates with another CAN-equipped vehicle, suspect vehicle side problem.



**Technical Service
Information Bulletin**
August 26, 2002

Title:

IMMOBILIZER KEY CODE RESET

Models:

**Applicable ES 300, GS 430, GS 300,
IS 300, & LX 470**

REVISED
TSIB
SS002-01

SPECIAL SERVICE TOOLS

TSIB REVISION NOTICE:

- August 26, 2005: The model years for each model have been specifically defined in the “Applicable Vehicles” section. The “Required SSTs” section has been updated.
- February 11, 2003: Model years for LX 470 revised to apply to 2001 and 2002 only.
- August 26, 2002: ES 300, GS 300, and IS 300 models added. Model years for GS 430 and LX 470 vehicles expanded to include 2002 and later. Diagnostic Tester software in Required Tools & Material updated to version 9.01a (or later).

Previous versions of this TSIB should be discarded.

Introduction Immobilizer Reset is a new feature that allows the registration of a new Master Key even if all original Master Keys are lost. Once the Immobilizer system is reset, all previously registered keys will be erased.

**Applicable
Vehicles**

MODEL YEAR	MODEL	ENGINE MODEL
2001 – 2005*	GS 430	3UZ-FE
2001 – 2002*	LX 470	2UZ-FE
2002 – 2003*	ES 300	1MZ-FE
2002 – 2005*	GS 300	2JZ-GE
2002 & Later*	IS 300	2JZ-GE

* Immobilizer Key Code Reset procedure is not available for prior model years.

NOTE:

Refer to TIS (Technical Information System) for the most current applicable vehicle information.

**Parts
Information**

PREVIOUS PART NUMBER	CURRENT PART NUMBER	PART NAME
N/A	Model Specific	Replacement Key (Master or Sub)

**Warranty
Information**

OP CODE	DESCRIPTION	TIME	OPP	T1	T2
N/A	Not Applicable to Warranty	–	–	–	–



Lexus Supports ASE Certification

Required SSTs	ITEM NO.	SPECIAL SERVICE TOOLS (SSTs)	PART NUMBER	QTY	DRW**	
	1	Lexus Diagnostic Tester Kit* NOTE: • All components from this kit/set are required • 12 Megabyte Diagnostic Tester Program Card (P/N 01002593-005) with version 13.0a Software (or later) is required		LEX220036	1	8
	2	CAN Interface Module Kit* NOTE: • All components from this kit/set are required		01002744	1	8

* Essential SSTs.

** Refers to drawer number in SST Storage System.

NOTE:

Additional Diagnostic Tester Kits, CAN Interface Modules, Program Cards, or other SSTs may be ordered by calling SPX/OTC at 1-800-933-8335.

Function Description The Immobilizer Reset function is a 5-step process:

1. Using the Diagnostic Tester, retrieve a “Seed Number” through the **OBD/MOBD Immobilizer** function.
 - A “Seed Number” is a unique number provided by the Diagnostic Tester and validated by TIS (Technical Information System) in order to return a Passcode.
2. Using TIS, select **Immobilizer Reset**, and complete the request form to retrieve a “Passcode Number.”
 - A “Passcode Number” is a unique number required by the Diagnostic Tester to reset the ECU allowing it to accept a new Master Key.
3. Enter the “Passcode Number” received from TIS into the Diagnostic Tester.
4. Confirm successful Immobilizer reset and new Master Key registration.
5. Register any additional customer keys.

**Key Code
Reset
Procedure**


NOTE:

Ensure that the Diagnostic Tester is equipped with the latest version of software (13.0a or later).

Connect the Diagnostic Tester to DLC3 and turn ignition ON.


1. Using the Diagnostic Tester, follow the screen flows below to retrieve the “Seed Number.” (**DO NOT DISCONNECT** the Diagnostic Tester from the vehicle during this process.)

FIGURE 2. DIAGNOSTIC TESTER SCREEN FLOW




**Key Code
Reset
Procedure
(Continued)**

2. Using TIS, select **Immobilizer Reset**, and complete the request form to retrieve a "Passcode Number."
 - A. Click on **Diagnostics**.
 - B. Click on **Immobilizer Reset**.



- C. Read the instructions on the screen and click on **Continue**.
(See Figure 4 below.)



**Key Code
Reset
Procedure
(Continued)**

D. Complete the request form and enter the “Seed Number” from the Diagnostic Tester. Click on **Submit** (Figure 5).

NOTE:

All fields must be completed.

FIGURE 5. REQUEST FORM ON TIS

E. TIS will now return the Passcode that needs to be entered into the Diagnostic Tester.

NOTE:

The Passcode given by TIS is only valid for one Immobilizer Reset Event.


FIGURE 8. RECEIVING PASSCODE FOR DIAGNOSTIC TESTER

**Key Code
Reset
Procedure
(Continued)**

3. Using the numbered keys (0–9) on the Diagnostic Tester, enter the “Passcode Number” received from TIS. (See Figure 7 below.) Press **ENTER** to clear all registered key codes.

NOTE:

Key Code Reset takes approximately 16 minutes.



4. Confirm successful Immobilizer reset and new Master Key registration by starting the vehicle.

NOTE:

If the vehicle starts, the new Master Key code is registered correctly.

If the vehicle does not start, perform the Immobilizer Reset function again.

5. All previously registered key codes have been erased except the Master Key used during “Key Code Reset.”
Register any additional customer keys by using “Key Registration.”
Each key will start the engine if registered correctly.
 - Please refer to TSIB No. SS006–99, “Scantool Immobilizer Key Code Utility,” for additional detail on this procedure.

FIGURE 8. KEY REGISTRATION





**Technical Service
Information Bulletin**

November 28, 2005

Title:

**CD SKIP VERIFICATION USING
LEXUS MASTER CD**

Models:

'01 – '06 All Models

SS003-05

SPECIAL SERVICE TOOLS

Introduction Lexus has developed a master CD to be used for customer complaints of the CD player skipping or CD player cannot read disc. This disc has been specially manufactured to test the performance of the Lexus CD players. Using this master CD will confirm that the radio exceeds Lexus' specification for CD player performance.

Applicable Vehicles • 2001 – 2006 model year **Lexus** vehicles.

Test Disc Specifications

TRACKS	DEFECT	MUSIC	TRACK TIME
1	None	Minuetto	3:15
2	0.8 mm Black Dot	2ème Gymnopédie	2:32
3	0.6 mm Black Dot	Overture Minature	3:02
4	None	Marche	2:36
5	None	Claire de Lune	3:09
6	None	Nocturne	3:12
7	0.4 mm Scratch	Danse de la Fée Dragée	2:28
8	0.6 mm Scratch	Danse Arabe	2:29
9	0.8 mm Scratch	Fantanisie-Improptu	2:51
10	1.0 mm Scratch	Hungarian Dance No. 5	2:02
11	None	Prelude <Raindrop>	3:38
12	None	Maiden's Prayer	3:15
13	Fingerprint 65 um	Valse des Fleurs	3:08
14	None	1ère Gymnopedie	2:54
15	Fingerprint 75 um	Danse Des Mirlitons	2:06

Warranty Information

OP CODE	DESCRIPTION	TIME	OFP	T1	T2
N/A	Not Applicable to Warranty	–	–	–	–



Lexus Supports ASE Certification

Required
SSTs

ITEM NO.	SPECIAL SERVICE TOOLS (SSTs)	PART NUMBER	QTY	DRW**
1	Lexus Master CD* NOTE: • All components from this kit/set are required	00002-07130-SCD	1	22

* Essential SSTs.

** Refers to drawer number in SST Storage System.

NOTE:

Additional SSTs may be ordered by calling SPX/OTC at 1-800-933-8335.

**Repair
Procedure**

1. Make sure the vehicle is stationary during the test.
2. Insert a compact disc (NOT the Lexus Master CD) to make sure the radio can accept and eject the disc without damaging it.
3. Check the Lexus Master CD for any unintended scratches or dirt. Wipe away dirt using a glass cleaning cloth. If the disc is damaged, order a replacement master CD.
4. Insert the Lexus Master CD and change to track number 9.
5. Play the track for one minute.
 - A. If skips are heard, replace the CD player.
 - B. If NO skips are heard, the CD player is working normally. Check the customer's CDs for scratches or other damage to the discs. Confirm that the customer is using a pre-recorded CD, NOT CD-Rs or CD-RWs as they may NOT have been burned properly.

NOTE:

- Tracks 1 – 8 and 11 – 14 are reference tracks. They can be used, but the conditions are less severe than track 9. Do NOT use tracks 10 and 15.
- Track 9 (0.8 mm scratch) is much more severe than the Lexus engineering specification in order to ensure customer satisfaction. If the customer's radio passes this test, a replacement radio will NOT improve the performance.
- This disc has been specially manufactured with a physical defect for the purposes of testing the CD player's performance. It is NOT possible to make copies of this disc that can be used to test the CD player's performance.



**Technical Service
Information Bulletin**

July 6, 2001

Title:

**DIAGNOSTIC TESTER
IMMOBILIZER FUNCTIONS**

Models:

**Applicable ES 330, GS 300, GS 430, GX 470,
LS 430, LX 470, RX 330, & SC 430**

TSIB
R E V I S E D
SS005-01
SPECIAL SERVICE TOOLS

TSIB REVISION NOTICE:

- August 26, 2005: The model years for each model have been specifically defined in the “Applicable Vehicles” section. The following vehicles have been added to the “Applicable Vehicles” section: ES 330, GS 300, GS 430, and RX 330. The “Required SSTs” section has been updated.
- January 9, 2003: GX 470 and LX 470 have been added to Applicable Vehicles. The “Required SSTs” section has been updated to the current version software. Screen flows revised (screen C and D) in Figures 1 (screen C and D), 2 (screen C), 3 (screen C), 4 (screen C and G), and 9 (screen A).
- The information contained in this TSIB supercedes the original SS005-01. Previous versions of this TSIB should be discarded.

Introduction

The Diagnostic Tester incorporates support for Immobilizer system service. This bulletin covers the following Immobilizer functions available using the Diagnostic Tester:

- Transponder Key Type
- Transponder Code Registration
- Transponder Code Erasure
- Transponder ECU Reset
- Transponder ECU Replacement
- Engine ECU Replacement

NOTE:

The available functions and procedures for the models listed in this TSIB differ slightly from previous models and other Immobilizer systems currently in use on Lexus vehicles.

**Warranty
Information**

OP CODE	DESCRIPTION	TIME	OFP	T1	T2
N/A	Not Applicable to Warranty	—	—	—	—



Lexus Supports ASE Certification

Applicable Vehicles

MODEL YEAR	MODEL	ENGINE MODEL
2001 & Later	LS 430	3UZ-FE
2002 & Later	SC 430	3UZ-FE
2003 & Later	GX 470	2UZ-FE
	LX 470	
2004 & Later	ES 330	3MZ-FE
	RX 330	
2006	GS 300 (w/o Smart Key)	3GR-FSE
	GS 430 (w/o Smart Key)	3UZ-FE

NOTE:

Refer to TIS (Technical Information System) for the most current applicable vehicle information.

Parts Information

PREVIOUS PART NUMBER	CURRENT PART NUMBER	PART NAME
N/A	Model Specific	Replacement Transponder Key (Master or Sub)

Required SSTs

ITEM NO.	SPECIAL SERVICE TOOLS (SSTs)	PART NUMBER	QTY	DRW**
1	Lexus Diagnostic Tester Kit* NOTE: • All components from this kit/set are required • 12 Megabyte Diagnostic Tester Program Card (P/N 01002593-005) with version 13.0a Software (or later) is required	 LEX220036	1	8
2	CAN Interface Module Kit* NOTE: • All components from this kit/set are required	 01002744	1	8

* Essential SSTs.

** Refers to drawer number in SST Storage System.

NOTE:

Additional Diagnostic Tester Kits, CAN Interface Modules, Program Cards, or other SSTs may be ordered by calling SPX/OTC at 1-800-933-8335.

Function Description	1. Transponder Key Type
	Before any Immobilizer functions are performed, verify the type of transponder key that you are attempting to use for the service operation. Some functions may only be performed with a registered Master Key.
	2. Transponder Code Registration
	This function allows the registration of additional transponder keys (Master or Sub) using a registered Master Key.
	3. Transponder Code Erasure
	This function allows the user to erase all the transponder keys except the registered Master Key used during this function.
	4. Transponder ECU Reset
	This function allows the registration of a new Master Key even if all original Master Keys are lost. Once the Immobilizer system is reset, all previous registered keys will be erased.
	5. Transponder ECU Replacement
	When the Transponder ECU is replaced, the transponder keys must be registered to the new ECU, auto registration closed, and ECU communication completed.
	6. Engine ECU Replacement
	When the Engine ECU is replaced, ECU communication must be completed to synchronize an encrypted security code between the engine and Transponder ECUs.

**Operation
Procedure**
**TRANSPONDER
KEY TYPE**

1. Transponder Key Type

Before any Immobilizer functions are performed, verify the type of transponder key that you are attempting to use for the service operation. Some functions may only be performed with a registered Master Key.


- Insert the current key into the ignition cylinder and turn to the **ON** position.

HINT:

The Immobilizer key blanks are preconfigured as Master or Sub Keys. Master Key blanks cannot be registered as Sub Keys nor can Sub Key blanks be registered as Master Keys. Also, the flat key is now enabled as a full function Master Key that must be registered.

- Follow the screen flow in Figure 1 to determine the key type.
- Key type and registration status will be indicated on the Immobilizer data list (Figure 1, screen E).
- “MATCH” = The key in the ignition cylinder matches this key type.
- “NOMATCH” = The key in the ignition cylinder does NOT match this key type.

FIGURE 1. TRANSPONDER KEY IDENTIFICATION



**Operation
Procedure
(Continued)**
**TRANSPOUNDER
CODE
REGISTRATION**

2. Transponder Code Registration

This function allows the normal registration of additional transponder keys (Master or Sub) using a registered Master Key.

NOTE:

This function requires the use of one registered Master Key. The use of a Sub Key will NOT complete Transponder Code Registration. Attempting registration of additional keys with only a Sub Key will result in errors and incomplete registration.

HINT:


The Immobilizer key blanks are preconfigured as Master or Sub Keys. Master Key blanks cannot be registered as Sub Keys nor can Sub Key blanks be registered as Master Keys. Also, the flat key is now enabled as a full function Master Key that must be registered.

- A. Insert a registered Master Key into the ignition cylinder and turn to the **ON** position.
- B. Follow the screen flow in Figure 2 to register new Master or Sub keys. It is possible to register up to 5 Master Keys and 3 Sub Keys.
- C. Be sure to follow the instructions on key insertion, ignition ON/OFF and key removal exactly as described on the Diagnostic Tester.

HINT:


The security indicator light reveals the following information:

- Always ON and NO key in IG* = Transponder ECU in Auto Registration mode
- Blinking and NO key in IG = Normal operation
- Blinking Code 21 = Transponder Code Registration failed
- Blinking Code 22 = Attempt was made to register an already registered Transponder Code



* Immediately after the transponder ECU is installed, the security indicator will blink.

**Operation
Procedure
(Continued)**
**TRANSPONDER
CODE
REGISTRATION**



**Operation
Procedure
(Continued)**
**TRANSPONDER
CODE ERASURE**

3. Transponder Code Erasure


This function allows the user to erase all the transponder keys except the registered Master Key used during this function.

NOTE:

This function requires the use of one registered Master Key. The use of a Sub Key will NOT complete Transponder Code Erasure.

- A. Insert a registered Master Key into the ignition cylinder and turn to the **ON** position.
- B. Follow the screen flow in Figure 3 below to erase all Master or Sub keys, except the registered Master Key used for this procedure.

FIGURE 3. ERASING TRANSPONDER CODES



**Operation
Procedure
(Continued)**
**TRANSPOUNDER
ECU RESET**

4. Transponder ECU Reset

This function allows the registration of a new Master Key even if all original Master Keys are lost. Once the Immobilizer system is reset, all previous registered keys will be erased. Use a new transponder Master Key to complete Transponder ECU Reset.

Immobilizer Reset

The Immobilizer Reset function is a 4-step process:


- A. Using the Diagnostic Tester, retrieve a “Seed Number” through the **OBD/MOBD Immobilizer** function.
 - A “Seed Number” is a unique number provided by the Diagnostic Tester and validated at TMS in order to return a Passcode.
- B. Using the TIS (Technical Information System) workstation, select **Immobilizer Reset**, and complete the request form to retrieve a “Passcode Number.”
 - A “Passcode Number” is a unique number required by the Diagnostic Tester to reset the ECU allowing it to accept a new Master Key.
- C. Enter the “Passcode Number” received from TIS into the Diagnostic Tester, register any additional customer keys, and close auto registration mode.
- D. Confirm successful Immobilizer reset and new Master Key registration.

**Operation
Procedure
(Continued)**
**TRANSPOUNDER
ECU RESET**

A. Connect the Diagnostic Tester to DLC3 and turn ignition **ON**.

- Using the Diagnostic Tester, retrieve a “Seed Number” through the **OBD/MOBD Immobilizer** function.
- Follow each step outlined in Figure 4.


FIGURE 4. RETRIEVING A SEED NUMBER




**Operation
Procedure
(Continued)**
**TRANSPOUNDER
ECU RESET**

B. Using the TIS workstation, select **Immobilizer Reset**, and complete the request form to retrieve a “Passcode Number.”

- Click on **Diagnostics**.
- Click on **Immobilizer Reset**.



c. Read the instructions on the screen and click on **Continue**.
(See Figure 6 below.)



**Operation
Procedure
(Continued)**
**TRANSPONDER
ECU RESET**

d. Complete the request form and enter the “Seed Number” from the Diagnostic Tester. Click on **Submit** (Figure 7).

NOTE:
All fields must be completed.

FIGURE 7. REQUEST FORM ON TIS

Immobilizer Reset Form

Complete the following form to receive a Passcode

Dealer Code: 99999

Dealer Name: Lexus Dealer Name

Technician SSN: 123-45-6789

Technician First Name: Tech First

Technician Last Name: Tech Last

Vehicle VIN: JT2DG12T000000000

Customer First Name: Cust First

Customer Last Name: Cust Last

Seed Number: 999999

SUBMIT **CLEAR**

e. TIS will now return the Passcode that needs to be entered into the Diagnostic Tester.

NOTE:
The Passcode given by TIS is only valid for one Immobilizer Reset Event.

FIGURE 8. RECEIVING PASSCODE FOR DIAGNOSTIC TESTER

Immobilizer Reset Passcode

Thank You Tech First Tech Last

This PASSCODE is valid for one Immobilizer Reset event

Your Passcode is: 17754

VIN: JT2DG12T000000000

Customer: Cust First Cust Last

Dealer: Lexus Dealer Name


**Operation
Procedure
(Continued)**
**TRANSPOUNDER
ECU RESET**

C. Using the numbered keys (0–9) on the Diagnostic Tester, enter the “Passcode Number” received from TIS into the Diagnostic Tester (see Figure 9 below). Press **ENTER** to clear all registered transponder codes except the Master key in the ignition cylinder.

NOTE:

- During the reset process do not remove the key from the ignition.
- This step takes approximately 16 minutes.

FIGURE 9. PASSCODE ENTRY



- Following a reset, the Transponder ECU is in auto registration mode.
- Auto registration mode allows 3 Master Keys and one Sub Key to register automatically.
- To register additional keys, remove the Master Key currently in the ignition. Insert keys (Master or Sub) into the ignition cylinder without turning the ignition on or off – simply insert and remove. (See Figure 9, screen D.)

NOTE:

- If 4 keys are registered at this time, auto registration mode is automatically closed.
- If less than 4 keys are registered at this time, auto registration mode must be closed manually by cycling the ignition ON/OFF more than 5 times in 10 seconds. (See Figure 9, screen E.)
- If more than 4 keys need to be registered, use Transponder Code Registration.

**Operation
Procedure
(Continued)**
**TRANSPOUNDER
ECU RESET**

D. Verify that keys are registered correctly by starting the engine with each newly registered key.

NOTE:

- If the vehicle starts, the new key code was registered correctly.
- If the vehicle does not start with any key, perform the Immobilizer Reset function again.
- If only one of the registered keys will not start the vehicle, attempt to register the key again following the Transponder Code Registration procedure (page 5 of this bulletin).

**TRANSPOUNDER
ECU
REPLACEMENT**

5. Transponder ECU Replacement

When the Transponder ECU is replaced, the transponder keys must be registered, auto registration closed, and ECU communication completed.

A. Replacement transponder ECUs are in auto registration mode. This allows transponder keys to automatically register as they are inserted into the ignition cylinder. It is possible to automatically register 3 Master Keys, and 1 Sub Key.

NOTE:


- If 4 keys are registered at this time, auto registration mode is closed.
- If less than 4 keys are registered at this time, auto registration mode must be closed manually by cycling the ignition ON/OFF more than 5 times in 10 seconds.
- If more than 4 keys need to be registered, use Transponder Code Registration procedure (page 5 of this bulletin).

B. Once auto registration mode is closed, ECU Communication must be performed between the transponder ECU and the Engine ECU. Complete ECU communication using the following steps:

- a. Insert registered Master Key into the ignition cylinder.
- b. Turn ignition ON (engine OFF).
- c. Short Tc and CG terminals of DLC3 using Diagnosis Check Wire (SST 09843-18040 or equivalent) and leave for 30 minutes. (See Figure 10.)

FIGURE 10. DLC3

Tc = Pin 13
CG = Pin 4



View of Connector Is From Passenger Compartment

- d. After 30 minutes, turn ignition OFF and remove check wire from DLC3
- e. Start the vehicle to confirm successful ECU communication.

NOTE:


If ECU communication is not completed correctly, the engine will not start and DTC B2799 will be set. DTC B2799 will be cleared after engine starts correctly.

**Operation
Procedure
(Continued)**
**TRANSPOUNDER
ECU
REPLACEMENT**

HINT:

The security indicator light reveals the following information:

- Always ON and NO key in IG* = Transponder ECU in Auto Registration mode
- Blinking and NO key in IG = Normal operation
- Blinking Code 21 = Transponder Code Registration failed
- Blinking Code 22 = Attempt was made to register an already registered Transponder Code



* Immediately after the transponder ECU is installed, the security indicator will blink.

**ENGINE ECU
REPLACEMENT**


6. Engine ECU Replacement

When the Engine ECU is replaced, ECU communication must be completed. ECU Communication must be performed between the transponder ECU and the Engine ECU. Complete ECU communication using the following steps:

- Insert registered Master Key into the ignition cylinder.
- Turn ignition ON (engine OFF).
- Short Tc and CG terminals of DLC3 using Diagnosis Check Wire (SST 09843-18040 or equivalent) and leave for 30 minutes. (See Figure 11.)

FIGURE 11. DLC3

Tc = Pin 13
CG = Pin 4



- After 30 minutes, turn ignition OFF and remove check wire from DLC3
- Start the vehicle to confirm successful ECU communication.

NOTE:

If ECU communication is not completed correctly, the engine will not start and DTC B2799 will be set. DTC B2799 will be cleared after engine starts correctly.



Technical Service Information Bulletin

April 29, 2005


STEERING INTERMEDIATE SHAFT NOISE

Models:

'03 ES 300, '04 – '05 ES 330

STEERING
ST001-05

Introduction Some customers may hear and feel a clunk, pop, or knock type noise when turning the steering wheel left or right. A new intermediate shaft has been developed to address this concern.



Applicable Vehicles

- 2003 model year **ES 300** vehicles.
- 2004 model year **ES 330** vehicles.
- 2005 model year **ES 330** vehicles produced **BEFORE** the Production Change Effective VINs shown below.

Production Change Information

MODEL	PRODUCTION CHANGE EFFECTIVE VIN
ES 330	JTHBA30G#55098506

Warranty Information

OP CODE	DESCRIPTION	TIME	OPP	T1	T2
ST4008	R & R Steering Intermediate Shaft	0.9	45220-33200	91	19

Applicable Warranty*:

This repair is covered under the Lexus Comprehensive Warranty. This warranty is in effect for 48 months or 50,000 miles, whichever occurs first, from the vehicle's in-service date.

* Warranty application is limited to correction of a problem based upon a customer's specific complaint.



Lexus Supports ASE Certification

Page 1 of 2

Parts Information	PREVIOUS PART NUMBER	CURRENT PART NUMBER	PART NAME	QTY
	45220-33200	45220-33240	Intermediate Shaft Assembly	1

Repair Procedure Prior to removing the steering intermediate shaft, make sure the steering wheel and front wheels remain stationary. Once the intermediate shaft is removed, do NOT allow the steering wheel to spin freely.

For information on replacing the steering intermediate shaft assembly, refer to the Technical Information System (TIS): 2003 – 2004 model year ES 330 Repair Manual: *Steering Column: Steering Column Assy: Overhaul*.



**Technical Service
Information Bulletin**
December 21, 2001

Title:

**REPAIR MANUAL SUPPLEMENT:
VEHICLE PULLING TO ONE SIDE**

Models:

All '02 – '06 Model

STEERING
REVISED
ST004-01

TSIB REVISION NOTICE:

- October 5, 2005: 2003 – 2006 model years have been added to Applicable Vehicles. A note has been added to the illustration in step 3.
- March 1, 2002: OP Codes updated in Warranty Information.

All previous versions of this TSIB should be discarded.

Introduction This bulletin contains general vehicle pulling diagnosis and repair procedures along with specific information to help correct pulling complaints.

This information supplements Repair Manual procedures when the symptoms are:

- The driver holds the steering wheel without exerting steering effort while driving straight ahead, and the vehicle drifts to the right or the left.
- While driving straight ahead, the driver has to steer either to the right or the left to maintain straight driving.

Applicable Vehicles • 2002 – 2006 model year **Lexus** vehicles.

Warranty Information

OP CODE	DESCRIPTION	TIME	OPN	T1	T2
ST1004	Preliminary Check & Road Test	0.6			
Combo A	Switch Front Tire/Wheel & Road Test	0.5			
Combo B	Reverse the Front One Side Tire	0.7			
Combo C	Check Front Wheel Alignment	1.2			
Combo D	Adjust Front Wheel Alignment	0.7			
Combo E	Adjust Camber Setting	0.7			
420091	Dismount and Mount Tire and Balance Wheel and Tire Assembly	0.5	45046-09020	31	99
Combo A	Each additional Wheel	0.3	42611-48030		

NOTE:

Above combination codes A, B, D and E include road test time.

Applicable Warranty*:

This repair is covered under the Lexus Comprehensive Warranty. This warranty is in effect for 12 months or 20,000 miles, whichever occurs first, from the vehicle's in-service date.

* Warranty application is limited to correction of a problem based upon a customer's specific complaint.



Lexus Supports ASE Certification

Contents This bulletin is divided into the following sections:



Wheel Alignment and Tire Characteristics	Pages 2-3
Repair Procedure Flow Chart	Page 4
Repair Procedures	
1. Important Notice	Page 5
2. Troubleshooting	Pages 5-6
3. Vehicle Pulling Caused by Wheel Alignment	Pages 6-7
4. Vehicle Pulling Caused by Tire Conicity	Pages 7-9
5. Camber Adjustment Method	Pages 9-10

**Wheel
Alignment &
Tire
Characteristics**

1. Relationship Between Wheel Alignment and Vehicle Pulling to One Side

When the cross camber or caster of the front wheel alignment is large, it can cause vehicle pulling.

WHEEL ALIGNMENT	DIRECTION OF VEHICLE PULLING
Camber	Vehicle pulls in direction of wheel with large camber value
Caster	Vehicle pulls in direction of wheel with small caster value



If the cross camber or caster is within the specified range (30' or less), noticeable vehicle pulling will not occur due to side-to-side differences in camber or caster.

NOTE:

On a flat road, if the cross camber or caster is 30' or less and the steering wheel is held without exerting steering effort for 100 m (109 yards) when driving at 100 km/h (62 mph), the alignment-induced drift distance is approximately 0.5 m (1.64 ft).

**Wheel
Alignment &
Tire
Characteristics
(Continued)**

2. Relationship Between Tire Characteristics and Vehicle Pulling to One Side


When radial tires are rotating, they have the characteristic of generating force in the lateral direction between the tire and the road surface. This lateral force is comprised of two factors:

- Ply-steer, which changes direction according to the rotation direction of the tires.
- Conicity, which is generated in a fixed direction regardless of the tire rotation direction.

If these lateral forces are too strong, vehicle pulling will occur.

A. Ply-Steer

Lateral force due to ply-steer is produced by the construction of the belts inside the tire tread. With radial tires, the wire of the belt is slanted as shown in the illustration below. Thus, it is in the lateral direction that tire tread easily changes shape (stretches), and lateral force is generated between the tire and the road surface in the lateral direction.




NOTE:

Lateral force from ply-steer prevents vehicle drift caused by road slant, so in many cases lateral force to the right is provided for left-handed steering vehicles.

B. Conicity


Conicity is lateral force resulting from uneven formation of the left and right sides of the tire. The direction the lateral force is exerted depends on the hardness of the side walls and the difference in height between the left/right sides of the tire.



NOTE:

- In the case of vehicle pulling caused by tires, the lateral force which is exerted as a result of conicity has the greatest effect. On a flat road, if the steering wheel is held without exerting steering effort for 100 m (109 yards) when travelling at 100 km/h (62 mph), the vehicle may drift as much as 1.5 m (5 ft).
- When vehicle pulling is due to conicity, the amount of drift can be reduced and the direction of drift can be changed by changing the location of the tire or reversing the tire when installing it on the wheel.

Repair
Procedure
Flow Chart



**Repair
Procedures****1. IMPORTANT NOTICE**

Before repairing vehicle pulling to one side, it is necessary to clearly identify the cause of the pulling condition. Frequently, the cause of the vehicle pulling to one side is diagnosed as wheel alignment. However, the actual cause may be lateral force generated by the tires. Performing wheel alignment when tire force is the cause could result in the wheel alignment being set at a value outside of specifications. This would then cause other problems such as uneven tire wear, etc.

2. Troubleshooting

First determine whether vehicle pulling to one side is caused by a wheel alignment problem or tire characteristics, then decide which repairs to make.

A. Perform the following checks and correct as necessary.

- a. Check tires for size, wear and for proper inflation pressure.
- b. Check whether the vehicle is noticeably tilted backward/forward or left/right.

NOTE:

Tilting of the vehicle produces a left-right difference in the camber and caster and can cause vehicle pulling to one side.

- c. Check brakes for dragging.

B. Confirm problem symptoms.

With the customer accompanying you, drive the vehicle to confirm if the customer's complaint involves vehicle pulling to one side or steering wheel off center. If the problem is steering wheel off center, adjust the front tie rods on the vehicle. **Refer to Lexus TSIB ST002-01.** Also check the direction of vehicle pulling and the extent of the pulling.

C. Decide if vehicle pulling is due to wheel alignment or tires.


- a. Switch the left and right front tires (If the tires are non-unidirectional).
- b. Conduct a drive test to check whether the direction that the vehicle pulls has changed.

SYMPTOM	PROBABLE CAUSE	CORRECTIVE ACTION
No change in vehicle pulling condition	Front wheel alignment	Proceed to Repair Procedure 3. Vehicle pulling caused by Wheel Alignment (Page 6)
Vehicle pulling eliminated	Tire conicity	Repair complete. Vehicle Pulling Caused by Tire Conicity (Page 3 and 6)
Vehicle pulling direction is reversed	Tire conicity	Proceed to Repair Procedure 4. Vehicle Pulling Caused by Tire Conicity (Page 7)

**Repair
Procedures**
(Continued)

Helpful hints to determine cause of vehicle pulling:


- The direction of lateral force from tire conicity becomes reversed when the left and right tires are switched. Therefore, if the pulling direction changes when the tires are switched, it can be concluded that vehicle pulling is caused by tire conicity.



- If the pulling direction does not change after the front tires are switched, the cause of vehicle pulling is not tire conicity. In this case, the likely cause is a front wheel alignment condition.

3. Vehicle Pulling Caused by Wheel Alignment

When it is determined by troubleshooting that the vehicle pulling to one side is caused by wheel alignment, perform repairs according to the following procedure.



**Repair
Procedures
(Continued)**

WHEN VEHICLE PULLS TO LEFT	WHEN VEHICLE PULLS TO RIGHT
Increase right front camber and decrease left front camber until vehicle pulling is eliminated	Increase left front camber and decrease right front camber until vehicle pulling is eliminated

NOTE:

- Keep the cross camber within 1° or less.
- Keep the camber of each wheel within specifications (+/-45' of center value).
- If adjustment exceeds the specifications, uneven tire wear will result.

4. Vehicle Pulling Caused by Tire Conicity

When it is determined by troubleshooting that the vehicle pulling to one side is caused by tire conicity, perform repairs according to the following procedures.

Indication of Tire Conicity as a Cause:

When the front tires are switched, the pulling direction changes. Proceed to STEP 1.

STEP 1:

Remove the front left tire from the wheel and reverse the tire. Then perform a road test and check for change in the pulling direction.


HINT:

By performing this operation, it can be checked whether the left or right tire exerts a stronger lateral force. Either tire can be reversed. Shown here is an example of the left tire reversed.


If Vehicle Pulls in the Same Direction: Go to STEP 2.

The lateral force generated by the right front tire is greater than the left tire, so the vehicle is pulling due to the lateral force of the right tire.

ORIGINAL TIRE POSITIONS



LEFT TIRE REVERSE INSTALLATION




Repair
Procedures
(Continued)


If Vehicle Pulls in the Opposite Direction: Go to STEP 2.

The lateral force generated by the left front tire is greater than the right tire, so the vehicle is pulling due to the lateral force of the left tire.

ORIGINAL TIRE POSITIONS



LEFT TIRE REVERSE INSTALLATION



If Vehicle Pull Is Eliminated: Repair Is Now Complete.

The lateral force generated by the left and right front tires is virtually the same, so the lateral force is neutralized and the vehicle travels straight ahead. The repair operation is now completed.

STEP 2:

Rotate the larger lateral force front tire with the rear tire and check the change in the vehicle pulling.

NOTE:

By shifting the front tire with the larger lateral force to the rear, the vehicle pulling level is usually reduced.

If Vehicle Is Still Pulling: Go to STEP 3.

If Vehicle Pull Is Eliminated: Repair Is Now Complete.

**Repair
Procedures
(Continued)**

STEP 3:

Adjust cross camber to eliminate vehicle pulling.

HINT:

If the tires are placed in the positions they were in during tire rotation when the least amount of vehicle pulling occurred, wheel alignment can be performed with a minimal amount of adjustment.

WHEN VEHICLE PULLS TO LEFT	WHEN VEHICLE PULLS TO RIGHT
Increase right front camber and decrease left front camber until vehicle pulling is eliminated	Increase left front camber and decrease right front camber until vehicle pulling is eliminated

NOTE:

- Keep the cross camber within 1° or less.
- Keep the camber of each wheel within specifications (+/-45' of center value).
- If adjustment exceeds the specifications, uneven tire wear will result.

5. Camber Adjustment Method

NOTE:



After the camber has been adjusted, inspect the toe-in.

NOTE:

The method of camber adjustment differs for different models, so please refer to the repair manual of the vehicle involved. (This is a sample from the RX 300 Repair Manual).

- Remove the front wheels and ABS speed sensor clamp.
- Remove the two nuts on the lower side of the shock absorber.
- Coat the threads of the nuts with engine oil.
- Temporarily install the two nuts.
- Adjust the camber by pushing or pulling the lower side of the shock absorber in the direction in which the camber adjustment is required.
- Tighten the nuts.

**Torque: 210 N·m
(2,150 kgf·cm, 155 ft·lbf)**



**Repair
Procedures
(Continued)**

G. Install the front wheels.
Torque: 103 N·m (1,050 kgf·cm, 76 ft·lbf)
H. Check the camber.

NOTE:

Adjusting value for the set bolts is 6' – 30' (0.1° – 0.5°). When making an adjustment of more than 45', replace the upper and lower steering knuckle set bolts with the adjusting bolts. If the camber is not within the specification, use the table shown to estimate how much additional camber adjustment will be required, and select the appropriate camber adjusting bolt.

I. Follow steps 5-a through 5-h again. Between steps 5-b and 5-c, exchange one or two selected bolts.

HINT:

When exchanging the two bolts, exchange one bolt each time.

Bolt	Set Bolt		Adjusting Bolt					
	11	•11	1 Dot	2 Dots	3 Dots			
Adjusting Value	1	2	1	2	1	2	1	2
15'	●			●				
30'	●				●			
45'	●							●
1°00'			●					●
1°15'				●				●
1°30'						●	●	

If Vehicle Pull Is Eliminated: Repair Is Now Complete.

If Vehicle Is Still Pulling: Contact Your Regional Office For Further Assistance.



**Technical Service
Information Bulletin**
May 5, 2003

Title:
ECM RESET MEMORY FUNCTION
Models:
'98 – '05 Applicable Models

TRANSMISSION & CLUTCH
R E V I S E D
TC002-03

TSIB REVISION NOTICE:

December 20, 2004: Applicable Vehicles section has been updated and modified, 2004 and 2005 model years added; and Reset Procedure 2 has been revised. Previous versions of this TSIB should be discarded.

Introduction Whenever an automatic transmission is replaced, overhauled or individual components are replaced, use this procedure to erase Engine Control Module (ECM, SAE term: Powertrain Control Module, PCM) "Learned Values" and minimize subsequent performance concerns.

CAUTION:

Failure to follow the following procedure may lengthen the time to readjust the "Learned Values," potentially resulting in performance concerns.

Applicable Vehicles Refer to **Reset Procedure 1** for the following vehicles with Electronically Controlled Automatic Transmissions:

- **1999 – 2003** model year **ES 300** and **RX 300** vehicles.
- **2003 – 2005** model year **GX 470** vehicles.
- **2004 – 2005** model year **RX 330** vehicles.

Refer to **Reset Procedure 2** for the following vehicles with Electronically Controlled Automatic Transmissions:

- **1998 – 2005** model year **GS 430/400/300, LS 430/400, LX 470**, and **SC 430/400/300** vehicles.
- **2001 – 2005** model year **IS 300** vehicles.

Warranty Information

OP CODE	DESCRIPTION	TIME	OPP	T1	T2
N/A	Not Applicable to Warranty	–	–	–	–



Required SSTs

SPECIAL SERVICE TOOLS (SSTs)	PART NUMBER	QUANTITY
Lexus Diagnostic Tester Kit*		01001270
CAN Interface Module Kit*		01002744
12 Megabyte Diagnostic Tester Program Card with version 12.01a Software (or later)*		01002593-005


* Essential SSTs.

NOTE:

Additional Diagnostic Tester Kits, CAN Interface Modules, Program Cards or other SSTs may be ordered by calling SPX/OTC at 1-800-933-8335.

Reset Procedure 1

1. Connect the Lexus Diagnostic Tester to the vehicle.
2. Reset the ECM (PCM). Refer to the procedures below.



3. Start the engine and warm it up to normal operating temperatures before test-driving.
4. Perform a thorough test drive with several accelerations from a stop with "light throttle" application until proper transmission shifting is verified.

Reset 1. Disconnect the negative battery cable for 5 minutes.

Procedure 2 2. Reconnect battery cable.

3. Start the engine and warm it up to normal operating temperatures before test-driving.

4. Perform a thorough test drive with several accelerations from a stop with “light throttle” application until proper transmission shifting is verified.



Technical Service Information Bulletin

August 4, 2003

Title:

ECM CALIBRATION: SHIFT FEELING ENHANCEMENT

Models:

'02 – '03 ES 300 & '04 – '05 ES 330

REVISED

TC004-03

TRANSMISSION & CLUTCH

REVISION NOTICE:

- April 1, 2005: 2004 – 2005 model year ES 330 vehicles have been added to Applicable Vehicles. Introduction and Note have been updated on page 1. Calibration Identification Chart has been updated to include ES 330 calibration IDs.
- August 6, 2003: There has been a change in Warranty Time.

Previous versions of this TSIB should be discarded.

Introduction

To improve the transmission shift feeling during specific operating modes, the Engine Control Module (SAE term: Powertrain Control Module/PCM) calibration has been revised. These improvements include:

- Reduced downshift lag when accelerating at speeds from 10 to 20 mph.
- Less gear hunting when driving on/off accelerator pedal at 20 to 30 mph (for example: during heavy rush-hour traffic).
- Improved response rate during heavy acceleration from a stop.

NOTE:

- Version 12.01a or later Diagnostic Tester software is required to perform this procedure.
- Before proceeding, verify the ECM (PCM) calibration has NOT been updated by checking for the Authorized Modifications Label (shown in step 1 of the Repair Procedure).
- Harsh ATM shifting may result if any Repair Procedure steps are omitted (specifically steps 2 and 4 of “Flash Reprogram ECM” on page 6).

Applicable Vehicles

- 2002 – 2003 model year **ES 300** vehicles.
- 2004 – 2005 model year **ES 330** vehicles.

Warranty Information

OP CODE	DESCRIPTION	TIME	OPP	T1	T2
EG5017	Recalibrate ECM Engine & Transmission	0.9	89666-3325# 89666-3344# 89661-33B3# 89661-33A4#	26	99

Applicable Warranty*:

This repair is covered under the Lexus Federal Emissions Warranty. This warranty is in effect for 96 months or 80,000 miles, whichever occurs first, from the vehicle's in-service date.

* Warranty application is limited to correction of a problem based upon a customer's specific complaint.



Lexus Supports ASE Certification

Parts Information

PREVIOUS PART NUMBER	CURRENT PART NUMBER	PART NAME	QTY
N/A	00451-00001-LBL	Authorized Modifications Label	1

NOTE:

Authorized Modification Labels may be ordered in packages of 25 from the Materials Distribution Center (MDC) through Dealer Daily Dealer Support Materials System or by calling the MDC at 1-800-622-2033.

Required SSTs

SPECIAL SERVICE TOOLS (SSTs)	PART NUMBER	QTY	DRW**
CAN Interface Module Kit* 	01002744	1	8
Lexus Diagnostic Tester Kit* 	01001270	1	8
12 Megabyte Diagnostic Tester Program Card with version 12.01a Software (or later)* 	01002593-005 (Component of 01001270)	1	

* Essential SSTs.

** Refers to drawer number in SST Storage System.

NOTE:

Additional Diagnostic Tester Kits, CAN Interface Modules, Program Cards, or other SSTs may be ordered by calling SPX/OTC at 1-800-933-8335.

Calibration Identification Chart


MODEL	ECM (CPU)	PREVIOUS CALIBRATION ID	NEW CALIBRATION ID
2002 – 2003 ES 300	Main	33323000	
		33323100	
		33323200	
		33341000	
		33341100	33387000
	Sub	33341200	
		33341300	
		33341400	
		53314000	
		53314100	
2004 – 2005 ES 330	Main	53314200	
		53328000	
		53328100	53343000
		53328200	
	Sub	53328300	
		53328400	
		33350000	
		33350100	33360200
		33360000	
		33360100	
		53334000	
		53340000	53340100

NOTE:

- 2004 model year ES 330 vehicles, which have been flash reprogrammed using the procedures in this TSIB, will contain upgraded 2005 model year OBD II logic and will require VIN input. Refer to the 2005 model year ES 330 Repair Manual information on the Technical Information System (TIS) when checking Powertrain Diagnostic Trouble Codes (DTCs) on 2004 model year ES 330 vehicles that have been reprogrammed.
- 2002 model year ES 300 vehicles, which have been flash reprogrammed using the procedures in this TSIB, will contain upgraded 2003 model year OBD II logic. Refer to the 2003 model year ES 300 Repair Manual information on the Technical Information System (TIS) when checking Powertrain Diagnostic Trouble Codes (DTCs) on 2002 model year ES 300 vehicles that have been reprogrammed.

Repair Procedure


1. Check for the Authorized Modifications Label affixed to the vehicle in the location shown in Figure 1. Confirm if ECM (PCM) calibration has been updated. If not the latest ECM (PCM) calibration — go to step 2.



**Repair
Procedure
(Continued)**

2. Connect the Diagnostic Tester to the vehicle and select CURRENT ECU CAL from the ECU REPROGRAM MAIN MENU. Determine the vehicle's current ECU calibration (see Figure 2).

- The sample screen prints seen below are the 12.01a software version and may differ from subsequent software versions.



NOTE:

- If Calibration ID matches “Previous Calibration ID” as shown in Calibration Identification Chart on page 3, proceed with flash reprogramming.
- If Calibration ID matches “New Calibration ID” as shown in Calibration Identification Chart, this vehicle has already been programmed. Refer to TIS for diagnostic procedures applicable to any stored DTCs.

3. If ECU calibration ID is not the same as the “New Calibration ID” listed previously, proceed to Flash Reprogram ECM (PCM).

4. Flash Reprogram ECM (PCM)

Follow the procedures outlined in Lexus TSIB No. SS001-01, “*ECU Flash Reprogramming Process*,” and flash the ECM (PCM) with the new calibration file update.

NOTE:

If the “Check Engine” light is ON when the ignition is turned back on to begin the reprogramming process, a scan tool cable problem exists. Refer to TSIB No. SS001-01, “*ECU Flash Reprogramming Process*.”

**Repair
Procedure**
(Continued)

5. **Reset the ECM (PCM) learned values using the diagnostic tester. Refer to the procedures below.**
 - The sample screen prints seen below are the 12.01a software version and may differ from subsequent software versions.

NOTE:

Failure to reset the ECM (PCM) memory will result in continued ATM shifting complaints.




Figure 3. ECM (PCM) Learned Values Reset

6. Follow the procedures outlined in TSIB No. EG012–04, “*Entering VIN During ECM (PCM) Replacement and/or DTC P0630*,” and write the VIN to the ECM (PCM).
7. Start the engine and warm it up to normal operating temperature before test–driving.
8. Test drive vehicle to confirm proper vehicle operation.
9. Enter the required information on the Authorized Modifications Label and affix it to the vehicle at the location shown in Figure 1 (page 4). The Authorized Modifications Label is available through the MDC, P/N 00451–00001–LBL.
10. Calibration update is complete.

NOTE:

- Select premium unleaded gasoline with an Octane Rating of 91 (Research Octane Number 96) or higher for optimum engine performance.
- The effect of the new calibration may become more apparent after several days of driving as the ECM (PCM) “learned values” are re-established from the customer’s driving.