

# AUTOMATIC TRANSMISSION

## CONTENTS

<b>GENERAL .....</b>	<b>2</b>	<b>TROUBLESHOOTING .....</b>	<b>2</b>
Outline of Changes .....	2		

### WARNING REGARDING SERVICING OF SUPPLEMENTAL RESTRAINT SYSTEM (SRS) EQUIPPED VEHICLES

#### WARNING!

- (1) Improper service or maintenance of any component of the SRS, or any SRS-related component, can lead to personal injury or death to service personnel (from inadvertent firing of the air bag) or to driver and passenger (from rendering the SRS inoperative).
- (2) Service or maintenance of any SRS component or SRS-related component must be performed only at an authorized MITSUBISHI dealer.
- (3) MITSUBISHI dealer personnel must thoroughly review this manual, and especially its GROUP 52B – Supplemental Restraint System (SRS) before beginning any service or maintenance of any component of the SRS or any SRS-related component.

#### NOTE

The SRS includes the following components: SRS-ECU, SRS warning lamp, air bag module, clock spring and interconnecting wiring. Other SRS-related components (that may have to be removed/installed in connection with SRS service or maintenance) are indicated in the table of contents by an asterisk (\*).

## GENERAL

### OUTLINE OF CHANGES

Vehicles with GDI-type 4G93 engines have a separate A/T-ECU and engine-ECU, in contrast to non-GDI-type 4G93 engines. To correspond to this, maintenance service procedures have been established for items which are different from before.

## TROUBLESHOOTING


### ROAD TEST

The test procedure is basically the same as that for '97 and prior vehicle models, except that the vehicle speed sensor system inspection procedures have been changed.

- Refer to P.23-6 for details on the vehicle speed sensor system inspection procedures.


### SHIFT PATTERN

#### UPSHIFT PATTERN




TFA203

## DOWNSHIFT PATTERN



TFA2034

## HOLD MODE PATTERN



TFA2035

## INSPECTION CHART FOR DIAGNOSIS CODE

Inspection procedures are basically the same as those for '97 and prior vehicle models.

Code	Diagnosis item		Reference page
11	Throttle position sensor system	Short circuit	23-14*
12		Open circuit	23-14*
14		Sensor maladjustment	23-14*
15	Oil temperature sensor system	Open circuit	23-14*
21	Crank angle sensor system	Open circuit	23-15*
22	Input shaft speed sensor system	Short circuit/open circuit	23-15*
23	Output shaft speed sensor system	Short circuit/open circuit	23-16*
25	Wide open throttle switch system	Short circuit	23-17*
26	Stop lamp switch system	Short circuit/open circuit	23-17*
31	Low and reverse solenoid valve system	Short circuit/open circuit	23-18*
32	Underdrive solenoid valve system	Short circuit/open circuit	23-18*
33	Second solenoid valve	Short circuit/open circuit	23-18*
34	Overdrive solenoid valve	Short circuit/open circuit	23-18*
36	Damper control clutch solenoid valve	Short circuit/open circuit	23-18*
41	1st gear ratio is not specified		23-19*
42	2nd gear ratio is not specified		23-20*
43	3rd gear ratio is not specified		23-21*
44	4th gear ratio is not specified		23-22*
46	Reverse gear ratio is not specified		23-23*
51	Abnormal communication with the engine-ECU		23-24*
52	Damper control clutch solenoid valve system	Defective system	23-18*
54	A/T Control relay system	Short circuit to earth/open circuit	23-24*
56	N range lamp system	Short circuit to earth	23-25*
71	Malfunction of A/T-ECU		23-25*

## NOTE

\*: Refer to '96 CARISMA Workshop Manual (Pub. No. PWDE9502).

**INSPECTION CHART FOR TROUBLE SYMPTOMS**

Inspection procedures are basically the same as those for '97 and prior vehicle models, except that the vehicle speed sensor system inspection procedures have been changed to correspond to the adoption of an electronic speedometer.


Trouble symptom		Inspection procedure No.	Reference page
Communication with MUT-II is not possible		1	23-26*
Driving impossible	Starting impossible	2	23-27*
	Does not move forward	3	23-27*
	Does not reverse	4	23-28*
	Does not move (forward or reverse)	5	23-28*
Malfunction when starting	Engine stalling when shifting	6	23-29*
	Shocks when changing from N to D and large time lag	7	23-29*
	Shocks when changing from N to R and large time lag	8	23-30*
	Shocks when changing from N to D, N to R and large time lag	9	23-31*
Malfunction when shifting	shocks and running up	10	23-31*
Displaced shifting points	All points	11	23-32*
	Some points	12	23-33*
Does not shift	No diagnosis codes	13	23-33*
Malfunction while driving	Poor acceleration	14	23-34*
	Vibration	15	23-34*
Inhibitor switch system		16	23-35*
Mode control switch system		17	23-35*
Idle position switch system		18	23-36*
Dual pressure switch system		19	23-36*
Vehicle speed sensor system		20	23-6

**NOTE**

\*: Refer to '96 CARISMA Workshop Manual (Pub. No. PWDE9502).

## INSPECTION PROCEDURE 20

Vehicle speed sensor system	Probable cause
The cause is probably a defective vehicle speed sensor circuit or a defective A/T-ECU.	<ul style="list-style-type: none"> <li>Malfunction of the vehicle speed sensor</li> <li>Malfunction of connector</li> <li>Malfunction of the A/T-ECU</li> </ul>



## SERVICE DATA REFERENCE TABLE

The following items have been added to correspond to the addition of vehicles with 4G93-GDI engine. Moreover, item No.57 (engine volumetric efficiency) is not included for vehicles with 4G93-GDI engine.

Item No.	Check item	Check requirement	Normal value
73	Target engine effective pressure	N range with accelerator pedal fully closed → depressed	Data changes

## CHECK AT THE A/T-ECU TERMINALS

Inspection procedures are basically the same as those for '97 and prior vehicle models, except that the input terminal No. for the vehicle speed sensor has been changed from terminal No.46 to terminal No.69.

Terminal No.	Check item	Check requirement	Standard value
69	Vehicle speed sensor	When stopped	0 V
		Move forward slowly	0 → 5 V alternating