

PGM-CARB Control System

Troubleshooting Flow Chart — TW Sensor

⑥ Self-diagnosis LED indicator blinks six times: Most likely a problem in the Coolant Temperature (TW) Sensor circuit.



