

PROBLEM SYMPTOMS TABLE

Flow chart No.	Symptom	See page
1	Black screen (Nothing displayed)	DI-1655
2	No sound even with POWER switch pressed. ("Audio OFF" on audio screen)	DI-1656
3	No navigation screen displayed when "MAP", "MENU", or "DESTINATION" switch pressed (Screen cannot be switched.)	DI-1658
4	No corresponding screen displayed when "AUDIO" or "A/C" switch pressed. (Screens other than above can be displayed.)	DI-1661
5	No navigation displayed, "Audio OFF" on audio screen and no audio sound.	DI-1662
6	Screen cannot be dimmed in night time.	DI-1664
7	Navigation screen not stabilized. (Synchronous error)	DI-1665
8	Color on navigation screen is unusual (RGB signal error)	DI-1667
9	Black screen appears when "MAP", "MENU" or "DESTINATION" switch pressed.	DI-1669
10	Sound of radio, cassette tape or CD only cannot be heard from speaker.	DI-1671
11	No sound (radio, cassette tape, CD) can be heard from driver side door speaker only.	DI-1673
12	Map DISC cannot be inserted.	DI-1676
13	MAP screen display does not appear. (Disc Caution screen does not change.)	DI-1677
14	Map is displayed in white or blue screen. (Switches and vehicle position mark are displayed.)	DI-1678
15	Navigation screen cannot change to night mode color.	DI-1679
16	Touch switch does not function. (Navigation screen only)	DI-1681
17	Vehicle position is deviated from correct point badly.	DI-1682
18	GPS mark does not appear.	DI-1685
19	No voice navigation.	DI-1687
20	Vehicle position mark rotates without control. (Map rotates without control)	DI-1688
21	Driving direction is opposite to moving direction of vehicle position mark.	DI-1690
22	Radio reception poor.	DI-1691
23	Cassette tape cannot be inserted.	DI-1693
24	Cassette tape cannot be ejected.	DI-1694
25	CD cannot be inserted.	DI-1695
26	CD cannot be ejected.	DI-1696
27	No AM, FM or CD screen is displayed.	DI-1697
28	Audio screen is not displayed.	DI-1699
29	Panel switches do not function.	DI-1701
30	Touch SW on the air conditioner screen does not function.	DI-1703
31	Turning Light Control switch "Tail" does not light up the panel switches.	DI-1704
32	Turning Light Control switch "Tail" does not light up the radio receiver switches.	DI-1705
33	Audio system cannot be operated with Steering PAD switch. (It can be operated with Panel/Touch switches.)	DI-1706
34	Audio system cannot be operated with air conditioner switches on Rear Controller. (It can be operated with Panel/Touch switches.)	DI-1709
35	Cellular mobile telephone screen is not displayed on multi display. (Navigation system screen is displayed.)	DI-1710

36	Cellular mobile phone is in abnormal operation. (Navigation system can be operated iwht voice recognition.)	DI-1712
37	Cellular mobile phone cannot be operatd with Steering pad switch. (It can be operated with Panel/ Touch switches.)	DI-1714