

WIRING DIAGRAMS

Fig. 5: MPI Control Unit (2.0L Turbo) (Grid 16-19)

1991 Mitsubishi Eclipse

For DIAKOM-AUTO <http://www.diakom.ru> Taganrog support@diakom.ru (8634)315187

Copyright © 1998 Mitchell Repair Information Company, LLC

Sunday, December 17, 2000 03:02PM

