



SERVICE BULLETIN

QUALITY INFORMATION ANALYSIS

OVERSEAS SERVICE DEPT. MITSUBISHI MOTORS CORPORATION

SERVICE BULLETIN		No.: MSB-97E17-501	
		Date: 1997-07-15	<Model> (EC,EXP)GALANT <M/Y> 97-10 (EA0)
Subject: CORRECTION OF ERRORS IN REGARD TO ACCELERATOR PEDAL POSITION SENOR BRACKET			
Group: ENGINE & EMISSION CONTROL		Draftno: 97-JY-001	
CORRECTION	OVERSEAS SERVICE DEPT	<i>R. Usami</i> R. USAMI - MANAGER QUALITY INFORMATION ANALYSIS	

1. Description:

This Service Bulletin informs you that errors have been corrected in regard to the accelerator pedal position sensor bracket (on RH drive car).

2. Applicable Manuals:

Manual	Pub. No.	Language	Page(s)
'97 GALANT Workshop Manual chassis	PWDE9611	(English)	17-7
	PWDS9612	(Spanish)	
	PWDF9613	(French)	
	PWDG9614	(German)	
	PWDD9615	(Dutch)	
	PWDW9616	(Swedish)	

3. Details:


Please refer to the attached page.

ACCELERATOR PEDAL POSITION SENSOR REMOVAL AND INSTALLATION

17100180018

Post-installation Operation

Adjusting the Accelerator Cable (Refer to P.17-3.)



Removal steps

1. Adjusting nut
2. Inner cable connection
3. Idle position switch connector
4. Accelerator pedal position sensor connector

5. Accelerator pedal position sensor assembly
6. Accelerator pedal position sensor bracket

<Correct>

