



# MEDIC UPDATE

## TECHNICAL SERVICE BULLETIN

SUBJECT:		No: <b>TSB-08-54-008</b>	
<b>CORRECTED CAUTION STATEMENT FOR HEAD-LIGHT MOTOR DRIVE TEST - SERVICE MANUAL REVISION</b>		DATE: <b>May, 2008</b>	
		MODEL: <b>2007-08 Outlander</b>	
CIRCULATE TO:	<input type="checkbox"/> GENERAL MANAGER	<input type="checkbox"/> PARTS MANAGER	<input checked="" type="checkbox"/> TECHNICIAN
<input checked="" type="checkbox"/> SERVICE ADVISOR	<input checked="" type="checkbox"/> SERVICE MANAGER	<input checked="" type="checkbox"/> WARRANTY PROCESSOR	<input type="checkbox"/> SALES MANAGER
<b>TSB Revision:</b> TSB-08-54-008			

## PURPOSE

In the On Vehicle Service section of the Headlight Automatic Levelling Motor Drive Test, the CAUTION statement is incorrect in the Applicable Service Manual. This Technical Service Bulletin provides the corrected information.


## AFFECTED VEHICLE(S)

2007-08 Outlander

## APPLICABLE MANUAL(S)

Manual	Pub. No.	Description
2007 OUTLANDER Service Manual	MSCD-007B-2007	Headlight Automatic Levelling Motor Drive Test. Pg 54Ac-177
2008 OUTLANDER Service Manual	MSCD-007B-2008	Headlight Automatic Levelling Motor Drive Test. Pg. 54A-232

## DETAILS



Copyright Mitsubishi Motors North America, Inc.

The information contained in this bulletin is subject to change. For the latest version of this document, go to the Mitsubishi Dealer Link, MEDIC, or the Mitsubishi Service Information website ([www.mitsubishitechinfo.com](http://www.mitsubishitechinfo.com)).