



MEDIC UPDATE

TECHNICAL SERVICE BULLETIN

SUBJECT:		No: TSB-08-54-005	
FOGLAMP/DAYTIME RUNNING LAMP MOUNTING BOLT DELETED - SERVICE MANUAL REVISION		DATE: April, 2008	
MODEL: 2007 -08 Outlander			
CIRCULATE TO:	<input type="checkbox"/> GENERAL MANAGER	<input checked="" type="checkbox"/> PARTS MANAGER	<input type="checkbox"/> TECHNICIAN
<input checked="" type="checkbox"/> SERVICE ADVISOR	<input checked="" type="checkbox"/> SERVICE MANAGER	<input checked="" type="checkbox"/> WARRANTY PROCESSOR	<input type="checkbox"/> SALES MANAGER
TSB Revision TSB-07-54-005			

PURPOSE

Effective with November 1, 2007 production, one of the four (4) mounting bolts for mounting the fog lamp/ daytime running lamp (DRL) to it's bracket has been eliminated. The corresponding weld nut on the bracket has also been eliminated.


This Technical Service Bulletin announces the changes and provides an illustration showing which fasteners are eliminated.

AFFECTED VEHICLE(S)

2007-08 Outlander built prior to November 1, 2007.

APPLICABLE MANUAL(S)

Manual	Pub. No.	Description/Page No.
2007 OUTLANDER Service Manual CD-ROM	MSCD-007B-2007	Fog Light Removal and Installation Daytime Running Light Removal and Installation
2007 OUTLANDER Service Manual PDF	MSSP-007B-2007	Fog Light Removal and Installation. Pg. 54Ac-186 Daytime Running Light Removal and Installation. Pg.54Ac-188



Mitsubishi Motors North America, Inc.

The information contained in this bulletin is subject to change. For the latest version of this document, go to the Mitsubishi Dealer Link, MEDIC, or the Mitsubishi Service Information website (www.mitsubishitechinfo.com).