



# **MEDIC UPDATE**

## **TECHNICAL SERVICE BULLETIN**

SUBJECT:		No: <b>TSB-08-54-007</b>	
<b>NEW ANTENNA BASE SECURING METHOD - SERVICE MANUAL REVISION</b>		DATE: <b>May, 2008</b>	
MODEL: <b>2007-08 Outlander</b>			
CIRCULATE TO:	<input type="checkbox"/> GENERAL MANAGER	<input type="checkbox"/> PARTS MANAGER	<input checked="" type="checkbox"/> TECHNICIAN
<input checked="" type="checkbox"/> SERVICE ADVISOR	<input checked="" type="checkbox"/> SERVICE MANAGER	<input type="checkbox"/> WARRANTY PROCESSOR	<input type="checkbox"/> SALES MANAGER
<b>TSB Revision TSB-08-54-007</b>			

### **PURPOSE**

The method for securing the radio antenna base to the vehicle has been changed in production effective August 1, 2007. The securing nut has been replaced with a bolt and spring (see illustration).




Due to this change, the removal and installation steps have been changed in the applicable Service Manual. This Technical Service Bulletin advises those changes. These changes apply to Affected Vehicles and vehicles where the antenna base is replaced with a new part.

### **AFFECTED VEHICLE(S)**

2007-08 Outlander built prior to August 1, 2007

### **APPLICABLE MANUAL(S)**

Manual	Pub. No.	Description	Attachment
2007 OUTLANDER Service Manual	MSCD-007B-07	Antenna Removal and Installation	1
2008 OUTLANDER Service Manual	MSCD-007B-08	Antenna Removal and Installation	1



Copyright Mitsubishi Motors North America, Inc.

The information contained in this bulletin is subject to change. For the latest version of this document, go to the Mitsubishi Dealer Link, MEDIC, or the Mitsubishi Service Information website ([www.mitsubishitechinfo.com](http://www.mitsubishitechinfo.com)).