

## GROUP 51

# EXTERIOR


### GENERAL

#### OUTLINE OF CHANGES

- The following service procedure has been revised as a dynamic damper has been added as the front bumper component <For Diesel>.
- The service procedure has been added due to the addition of the DI-D mark.

### FRONT BUMPER<FOR DIESEL>

#### DISASSEMBLY AND REASSEMBLY




#### Disassembly steps

1. Radiator grille, R.H.	6. Dynamic damper
2. Radiator grille, L.H.	7. Form
3. Bumper protector	8. Fog lamp cover
4. Fog lamp	9. Under grille
5. Bumper reinforcement	10. Bumper face


## MARK

### REMOVAL AND INSTALLATION

&lt;Sedan&gt;



&lt;Hatchback&gt;



AY0019BN


►A◄ 1. DI-D MARK

### INSTALLATION SERVICE POINT

#### ►A◄ MARK INSTALLATION

##### (1) DI-D MARK

&lt;Sedan&gt;



&lt;Hatchback&gt;

