


AB302081AB

Symbol	Operation description
● ● ● ●	Spot welding
■ ■ ▲ ▲	MIG plug welding (■ : indicates two panels to be welded ▲ : indicates three panels to be welded)
+++	MIG spot welding
	MIG arc welding (continuous)
○○○○○○○○	Braze welding
	Anti-corrosion agent application locations (Use access holes to apply liberally to butt-welded joints.)