



AB400821AB

Symbol	Operation description
● ● ● ●	Spot welding
■ ■ ▲ ▲	MIG plug welding (■: indicates two panels to be welded ▲: indicates three panels to be welded)
+ + + +	MIG spot welding
	MIG arc welding (continuous)
○ ○ ○ ○ ○ ○ ○ ○	Braze welding
	Anti-corrosion agent application locations (Use access holes to apply liberally to butt-welded joints.)