


Timing mark  
(Slot portion)

Timing mark  
(Cylinder block  
protrusion)



Crankshaft sprocket

AC609340AB