

Diagram of Section A-A showing a mechanical assembly with labels 2, 4, 6, and Claw. The diagram illustrates a vertical assembly with a central shaft and various components. Label 2 points to a component at the bottom, label 4 points to a component on the right side, label 6 points to a component at the top, and two arrows labeled 'Claw' point to specific features on the assembly.

Section B – B

Claw

5

Section C – C

The diagram shows a vertical structural member. A horizontal bracket, labeled 'Claw', is attached to the left side of the member. Two points are marked on the member: point '2' is located on the lower half, and point '4' is located on the upper half, above the claw. The member has a slight curve at the bottom.

Diagram illustrating a double claw assembly. The assembly consists of two main components, labeled 2 and 3, which are joined by a central horizontal bar. Each component has a curved, hook-like end labeled 'Claw'. The diagram shows the assembly in a side view, with the claws pointing outwards.

