



Side turn-signal lamp assembly



Section A - A



MB990784

AC804772AB