

# insider info.

## **Don't Touch That Screw!**

Be advised that the throttle stop screw adjustment cannot be reset in the field. It is preset by the manufacturer, using equipment that is far more expensive and accurate than the screwdriver that may be used to misadjust it. The only fix for a throttle body where the throttle stop screw has been tampered with is to replace the throttle body unit. That's a good enough reason to rename the throttle stop screw the *Do Not Touch Screw*.