

insider info.

Replacement Wiper Blade Refills

This information pertains to wiper blade refills, Subaru P/N SOA473W319 and SOA473W321.

If a customer complains of the wiper hitting the "A" pillar after installing these refills, check to make sure they are correctly installed. They are directional.

The refills have a metal "locking clip" on one end. When the refills are properly installed, the "locking clip" should be on the end of the wiper facing the passenger side of the vehicle. In other words, if the wipers were intentionally stopped in mid-cycle to ease refill installation, the "locking clip" should be at the end closest to the roof, not the hood.