



### Shifter Rattle

If you encounter a shifter rattle complaint on a 1996/7 Legacy Outback or a 1998 Forester, the parts to repair this problem are available through Subaru parts departments. For the 1996 Legacy Outback, order modified spacer, P/N 35045AC040. For the 1998 Forester and 1997 Legacy, order the modified bolt, P/N 35045FC000. Refer to the illustrations for installation locations.