

insider info.

A/C Inoperative Impreza/Forester Vehicles

If you encounter an Impreza or Forester vehicle with the A/C not working or working 'backwards,' check to see if the vehicle has the correct evaporator thermosensor installed. The evaporator thermosensors for these vehicles work opposite each other. Installing an Impreza evaporator thermosensor into a Forester will cause the A/C system to run with the A/C switch in the OFF position. The same thing can happen if the situation is reversed (Forester thermosensor installed in an Impreza.) Also, switching model years within the same vehicle, (i.e. 1998 Impreza part installed in a 1997 Impreza), can cause the system to operate backwards. So, when replacing evaporator thermosensors in Impreza and Forester vehicles, always stay with the correct model and year.