

# insider info.

## **SVX Evaporator Thermosensor Intake Sensor**

Should you have a failure of the Evaporator Thermosensor (also known as the Intake Sensor) in an SVX, the new part you receive may be physically different than the part you are replacing. The new part requires contact with the fins of the evaporator, so removal of the evaporator is required in order to install it.

There may be a small resistor harness between the old sensor and the vehicle's harness. If there is, it should be removed prior to installation of the new thermo-sensor. Failure to remove this resistor may cause insufficient cooling under certain conditions of temperature and humidity.