


## 12. Front Accessory Power Supply Socket

### A: WIRING DIAGRAM

<Ref. to WI-120, WIRING DIAGRAM, Front Accessory Power Supply Socket System.>

### B: REMOVAL

- 1) Disconnect the ground cable from battery.
- 2) Remove the instrument panel lower. <Ref. to EI-51, INSTRUMENT PANEL, LOWER, REMOVAL, Center Console.>
- 3) Disconnect the harness connectors and remove the front accessory power supply socket.



### C: INSTALLATION

Install in the reverse order of removal.