


(21) キー抜き忘れ警告ブザー回路

直流電源回路参照	
FB-10 F/B ヒューズ No.13 (B)	FB-6 F/B ヒューズ No.6 (B)



F14 2極

F65 32極

F34 2極

b: i201 16極黒

i77 6極

