

Front Accessory Power Supply Socket System


WIRING SYSTEM

41.Front Accessory Power Supply Socket System

A: WIRING DIAGRAM

FAPS-01

FAPS-01



(R274)

(R275)

1
2

(R229)

1	2		3	4
5	6	7	8	9
10	11	12	13	14

(B97)

1	2	3	4		5	6	7	8	9
10	11	12	13	14	15	16	17	18	19
20	21	22	23	24	25	26	27	28	29

(B225) (BLACK)

1	2	9	13	17	21
3	4	10	14	18	22
5	6	11	15	19	23
7	8	12	16	20	24
25	29	33	37		
26	30	34	38		
27	31	35	39	40	

RELAY BLOCK

WI-16083