

WIRING SYSTEM

48.Speedometer System

A: WIRING DIAGRAM

Diagram illustrating the POWER SUPPLY CIRCUIT. The circuit is represented by a rectangular box divided into two sections. The top section is labeled "POWER SUPPLY CIRCUIT". The bottom section contains the text "FB-36" and "F/B FUSE NO. 5 (IG)". Below the box is a vertical line with a small circle at the bottom, labeled "JOINT".

