

DIAGNOSTIC TROUBLE CODE CHART

DTC No. (See Page)	Detection Item	Trouble Area
B2795 (DI-336)	Unmatched key code	• Key • Unregistered key inserted before
B2796 (DI-337)	No communication in immobiliser system	• Key • Transponder key coil • Amplifier • Wirehanness • Engine and ECT ECU
B2797 (DI-340)	Communication malfunction No.1	• Communication contents • Unregistered key inserted before
B2798 (DI-344)	Communication malfunction No.2	• Key • Transponder key coil • Amplifier • Wire haness • Engine and ECT ECU

HINT:

To reduce the unnecessary exchange of Engine and ECT ECU, check that a trouble occurs with the original Engine and ECT ECU at the time of exchanging Engine and ECT ECU and the trouble will disappear with a new Engine and ECT ECU.