


INSPECTION

1. VEHICLES NOT INVOLVED IN A COLLISION

- (a) Perform a diagnostic system check (see page [DI-1851](#)).
- (b) With the curtain shield airbag assembly installed on the vehicle, perform a visual check. If there are any defects as mentioned below, replace the front pillar garnish or roof headlining assy with a new one:
Cuts, minute cracks or marked discoloration on the front pillar garnish or roof headlining assy around the curtain shield airbag assembly.

2. VEHICLE INVOLVED IN A COLLISION AND AIRBAG IS NOT DEPLOYED

- (a) Perform a diagnostic system check (see page [DI-1851](#)).



- (b) With the curtain shield airbag assembly removed from the vehicle, perform a visual check. If there are any defects as mentioned below, replace the curtain shield airbag assembly with a new one:
 - Cuts, tears and cracks, or marked discoloration on the curtain shield airbag assembly.
 - Cracks or other damage to the connector.

CAUTION:

For removal and installation of the curtain shield airbag assembly, see page [RS-111](#) and [RS-114](#). Be sure to follow the correct procedure.