

B: INSTALLATION

Overall view




For locations marked by " \star ": the welding method and the number of welding points are the same on the left and the right.

• Views 1



For locations marked by " \star ": the welding method and the number of welding points are the same on the left and the right.

• Views 2



For locations marked by " \star ": the welding method and the number of welding points are the same on the left and the right.