
B: INSTALLATION

• RH



- (A) 40 mm (1.57 in)
- (1) 1 point

(3) 2 points

(5) 2 points (service)

(2) 5 points

(4) 6 points

(6) 1 point (service)

For part marked by "a": Anticorrosion wax shall be applied thoroughly on the back side of continuous welding portion.