

# Troubleshooting

## Troubleshooting Flowchart — Cooling Fan

NOTE: Check for blown No.2 (15 A), No.39 (15 A), No.8 (7.5 A) fuse

