


Timing mark



Exhaust camshaft
sprocket

Inlet camshaft
sprocket

ACA00956AB