


Areas on throttle valve to apply molybdenum disulfide



AKA00160AB