


Front Accessory Power Supply Socket System

WIRING SYSTEM

20. Front Accessory Power Supply Socket System

A: WIRING DIAGRAM



WI-39169

b

b

LIST OF CONNECTORS



WI-35751