

Shift Lock Control System


WIRING SYSTEM

52.Shift Lock Control System

A: WIRING DIAGRAM

a

a



OP : WITHOUT PUSH BUTTON START


WP : WITH PUSH BUTTON START

*1 : WITHOUT PUSH BUTTON START : B/W
WITH PUSH BUTTON START : Y/R

WI-45861

Shift Lock Control System

WIRING SYSTEM



OP : WITHOUT PUSH BUTTON START
OEX : WITHOUT EyeSight AND X MODE
WEX : EXCEPT FOR MODEL WITHOUT EyeSight AND X MODE

*1 : TERMINAL No. OPTIONAL ARRANGEMENT
 *2 : TERMINAL No. OPTIONAL ARRANGEMENT AMONG 7, 8, 9, 10, 11 AND 12
 *3 : WITHOUT EyeSight AND X MODE : BR/R
 EXCEPT FOR MODEL WITHOUT EyeSight AND X MODE : W/R

WI-45862


Shift Lock Control System

WIRING SYSTEM

C

C

LIST OF CONNECTORS



WI-40955