

Front Accessory Power Supply Socket System




WIRING SYSTEM

30.Front Accessory Power Supply Socket System

A: WIRING DIAGRAM

FAPS-01

FAPS-01



WI-22959