

Rear Accessory Power Supply Socket System


WIRING SYSTEM

41. Rear Accessory Power Supply Socket System

A: WIRING DIAGRAM

RAPS-01

RAPS-01



(R263)
(R264)

(R227) (BLACK)
(R228) (BLACK)

(R254)

1	2	3	4	5	6
7	8	9	10	11	12

1	2	3	4	5	6
5	6	7	8	9	10
10	11	12	13	14	

WI-11798