

GROUP 51

EXTERIOR


GENERAL

OUTLINE OF CHANGES



The following maintenance service points have been established to correspond to the addition of vehicles with 4G93-GDI engine. Maintenance service procedures not listed below are the same as before.

MARKS

REMOVAL AND INSTALLATION



18U0498

18U0499
00007147

1. GDI MARK
2. CARISMA GDI MARK