



REPAIR WELDS



(With the quarter outer panel and fuel filler neck bracket removed)



A

AB302145 AB