



Canvas lost and
rubber exposed

Missing
Tooth



AK202796AB