




A line drawing of a car's interior floor area, specifically the driver's side footwell. Two rectangular inspection lids are shown, one above the other. A line points from the text 'Inspection lid' to the top lid. The drawing shows the floor pan, the base of the seat, and the lower part of the dashboard and center console.

Inspection lid

AC804776AB