




SERVICE BULLETIN

QUALITY INFORMATION ANALYSIS
OVERSEAS SERVICE DEPT. MITSUBISHI MOTORS CORPORATION

SERVICE BULLETIN		No.: MSB-97E52-004	
		Date: 1998-02-15	
Subject: CHANGE IN ATTACHMENT POSITION OF SRS AIR BAG CAUTION LABEL		<Model> (EC,EXP)L200 (K60,K70)	<M/Y> 97-10
Group: SUPPLEMENTAL RESTRAINT	Draftno: 97-SY-029		
INFORMATION	OVERSEAS SERVICE DEPT	 R. USAMI - MANAGER QUALITY INFORMATION ANALYSIS	

1. Description:

This Service Bulletin informs you of change in attachment position of the SRS air bag caution label.

2. Applicable Manuals:

Manual	Pub. No.	Language	Page(s)
L200 Technical Information Manual	PYTE96E1	(English)	6-10
L200 Workshop Manual	PWTE96E1	(English)	52B-22
	PWTS96E1	(Spanish)	
	PWTF96E1	(French)	
	PWTG96E1	(German)	

3. Effective Date:

From October 1997


4. Details:

Interior - Supplemental Restraint System (SRS), page 2
SRS - Warning / Caution Labels, page 3

WARNING/CAUTION LABELS


A number of caution labels relating to the SRS can be found in the vehicle, as shown in the following illustration. Follow label instruction when servicing SRS.

Steering wheel




19N0245

Air bag module




19V0059

Clock spring




19X0015

Glove box




19V0060

Sun visor




19V0061

SDU




19V0062

Hood



19V0063

Frame <2WD>




19V0064

Frame <4WD>

<Added>


*1



19V0065

<Added>

Frame <4WD>^{*2}




NOTE

Label I is attached in position either at Frame <4WD>^{*1} or at Frame <4WD>^{*2}


WARNING/CAUTION LABELS

A number of caution labels relating to the SRS are found in the vehicle, as shown in the following illustration. Follow label instructions when servicing


SRS. If labels are dirty or damaged, replace them with new ones.

Steering wheel


19N0245

Air bag


19V0059

Clock spring


19X0015

Glove box


19V0060

Sun visor


19V0061

SDU

19V0062

Hood

19V0063


Frame <2WD>

19V0064

Frame <4WD>

<Added>


*1



19V0065

<Added>

00005050

Frame <4WD>²

V0205AA

NOTE

The label for Frame <4WD> is attached in position either at Frame <4WD>¹ or at Frame <4WD>².